

Basic Condition Guide


| • | Report ID: | 25,005,748 | Version: | 1 |
|---|------------|-------------|----------|---|
| | Created: | 29 Dec 2025 | | |

| Make: | KIA | Model: | Sportage |
|---|-------------|------------------|-------------------|
| Body Style: | SUV | Year: | 2025 |
| Rego No.: | RAJ330 | Rego Expiry: | 08 Jan 2027 |
| WoF Expiry: | 09 Jan 2028 | Odometer: | 42,524 Kms |
| Good No.: | 25005748 | VIN: | KNAPV81GMS7212069 |
| Next Service: | 42,000 Kms | Service History: | Yes |
| Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or | | | |

diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

* = DecalsW = Significant scuffs S = ScratchR = RustC = CrackD = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

| Conditions During Body Inspection | Wet | | |
|---|-----|--|--|
| Under Carriage and Under Bonnet Inspection Comments | | | |

| Interior Comments | | |
|-------------------|---------|--|
| Seats: | Average | |
| Carpets: | Average | |
| Panels: | Average | |
| Dashboard: | Average | |

General Comments

AC and heating systems good temperature along with reversing camera and sat nav working at time of inspection.

| Road Conditions During Test Drive | | Wet |
|-----------------------------------|----------------|--------------|
| Engine Timing Mechanism | | Timing Chain |
| Evidence of Cam Belt Replacement | | Yes No Kms |
| Inspected by: | Finlay Lemmens | |
| Published by: | Amanda Loader | |
| Inspection Date: | 29 Dec 2025 | |

| nave read and understood | | | |
|--------------------------|------|--|--|
| nis condition quide: | NAME | | |

| | ОК | Requires Attention | N/A |
|--------------------------------|----------|-----------------------|----------|
| Engine | OK | Attention | 13/73 |
| Oil level | | | |
| Smoke & fumes | / | | |
| Engine performance | _ | | |
| Noise | V | | |
| Coolant condition | / | | |
| Cooling performance | / | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | / | | |
| Clutch | | | 1 |
| CV joints | / | | |
| Wheel bearings | / | | |
| Brakes | | | |
| Performance | / | | |
| Hand brake | / | | |
| Tyres (lowest observed tread d | epth of | tyres) | |
| Left front | | | 1.0 mm |
| Right front | | | 1.0 mm |
| Left rear | | | 1.0 mm |
| Right rear | | | 1.0 mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | / | | |
| Steering performance | / | | |
| Shock absorbers | / | | |
| Air Conditioning / Heater | | | |
| Operation | / | | |
| Electrical / Accessories | | | |
| Head lights | / | | |
| Tail lights | / | | |
| Indicators | ✓ | | |
| Dashboard warning lights | / | | |
| Wipers (front & rear) | / | | |
| Window winder FL | / | | |
| Window winder FR | V V | | |
| Window winder RL | | | |
| Window winder RR | V V | | |
| Rear view mirrors | / | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | | | ' |
| Number of keys | 2 | , | · |
| Central locking | / | | |
| Remote locking | / | | |
| Sat. nav. (basic test only) | / | | |
| Reversing camera | | | |