


| | | | |
|---------------|-------------|------------------|-------------------|
| Make: | Mazda | Model: | CX-5 |
| Body Style: | SUV | Year: | 2022 |
| Rego No.: | PDQ627 | Rego Expiry: | 16 May 2026 |
| WoF Expiry: | 27 May 2026 | Odometer: | 92,622 Kms |
| Good No.: | 25005965 | VIN: | JM0KF2W7A00766470 |
| Next Service: | 103,000 Kms | Service History: | Yes |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = Scratch R = Rust C = Crack * = Decals W = Significant scuffs
D = Dent PT = Paint defect P = Pin dent SC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection Dry

Under Carriage and Under Bonnet Inspection Comments

Interior Comments

| | |
|------------|---------|
| Seats: | marks |
| Carpets: | Average |
| Panels: | Average |
| Dashboard: | Average |

General Comments

Air conditioning and heating systems along with reverse camera working at time of inspection.

| | | | | | |
|-----------------------------------|--------------------------|-----|--------------------------|----|-----|
| Road Conditions During Test Drive | Dry | | | | |
| Engine Timing Mechanism | Timing Chain | | | | |
| Evidence of Cam Belt Replacement | <input type="checkbox"/> | Yes | <input type="checkbox"/> | No | Kms |
| Inspected by: | Gary Adams | | | | |
| Published by: | Amanda Loader | | | | |
| Inspection Date: | 12 Jan 2026 | | | | |

I have read and understood
this condition guide:

NAME

| | | | |
|------------|-------------|----------|---|
| Report ID: | 25,005,965 | Version: | 3 |
| Created: | 16 Jan 2026 | | |

| | OK | Requires Attention | N/A |
|---|-----|--------------------|-----|
| Engine | | | |
| Oil level | ✓ | | |
| Smoke & fumes | ✓ | | |
| Engine performance | ✓ | | |
| Noise | ✓ | | |
| Coolant condition | ✓ | | |
| Cooling performance | ✓ | | |
| Radiator / Hoses (visual) | ✓ | | |
| Transmission | | | |
| Operation | ✓ | | |
| Noise | ✓ | | |
| Clutch | | | ✓ |
| CV joints | ✓ | | |
| Wheel bearings | ✓ | | |
| Brakes | | | |
| Performance | ✓ | | |
| Hand brake | ✓ | | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | | 5.0 mm | |
| Right front | | 5.0 mm | |
| Left rear | | 4.0 mm | |
| Right rear | | 4.0 mm | |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | ✓ | | |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | ✓ | | |
| Window winder FL | ✓ | | |
| Window winder FR | ✓ | | |
| Window winder RL | ✓ | | |
| Window winder RR | ✓ | | |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | ✓ | | |
| CD (basic test only) | | | ✓ |
| Number of keys | 2 | | |
| Central locking | ✓ | | |
| Remote locking | ✓ | | |
| Sat. nav. (basic test only) | | | ✓ |
| Reversing camera | ✓ | | |

SIGNATURE