

I have read and understood this condition guide.

Report ID: 25,007,523 2 Version: 09 Apr 2025 Created:

Signature: .....

Make:	Audi	Model:	Q7	Body Style:	SUV		Pass	Fail	N/A
Year:	2016	<b>Registration:</b>	QNL149	<b>Reg Expiry:</b>	20 Sep 2024	Engine	1		
WoF Expiry:	03 Apr 2026	Odometer:	144,900 Kms	Good No:	25007523	Oil level	~		
VIN:	WAUZZZ4M7GD067287	Next Service:	152,000kms	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	S					Performance	~		
Key:	Ľ L	-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust PT = paint defect						Transmission			
						Operation	~		
						Noise	~		
C = crack						Clutch			~
P = pin dent	s dle				2416	CV joints	~		
* = decals SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
					Left front	6.0 mm		mm	
						Right front	7	.0	mm
						Left rear	6	.0	mm
Conditions During Body Inspection: Dry						Right rear	Right rear 6.0		mm
						Spare N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension	-		
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
	Avelage					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
Conoral (	ammanta					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Air conditioning and heating systems, along with reverse camera and navigation working at inspection						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Timing Chain						Remote locking	~		
						Sat. Nav. (basic test only)	~		
		.cment. N	lot Applicable	11115.		Reversing camera	~		
Inspected by: Gary Adams Date: 17 Dec 2024									

Name: .....