

Report ID: 25,009,392 8 Version: 08 May 2025 Created:

Make:	Hyundai	Model:	lmax	Body Style:	People Mover		Pass	Fail	N/A
Year:	2021	<b>Registration:</b>	NKZ978	<b>Reg Expiry:</b>	21 Apr 2025	Engine			·
WoF Expiry:	01 Apr 2026	Odometer:	203,975 Kms	Good No:	25009392	Oil level	~		
VIN:	KMHWH81KMMU191037	Next Service:	210,000kms	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch D = dent B = rust						Transmission			
						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints			~
*= decais						Wheel bearings	~		
SC = stone chips						Brakes			<u> </u>
W = significant scuffs						Performance 🖌			
Rody Inspection Commonte Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	· ·		
Body Inspection Comments						<b>Tyres</b> (lowest observed tread depth of tyres)			
						Left front	nt 6.0		mm
						Right front	6.0 m		mm
						Left rear	7.	.0	mm
Conditions During Body Inspection: Dry						Right rear	7.	.0	mm
						Spare	are Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Tested passed at time of inspection						Suspension performance	~		
rested pass	sed at time of inspection	11				Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			<u> </u>
						Operation 🖌			
Interior Comments						Electrical / Accessories	I		L
Seats	Average					Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
	· ·					Window winder FR	~		
General Comments						Window winder RL			~
Air conditioning and heating systems, working along with reverse camera at time of inspection.						Window winder RR			~
Dashboard	screen cracked					Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	3		
Road Con	ditions During Tes	Central locking	~						
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
							25		
Inspected by: Gary Adams Date: 18 Mar 2025									
I have read and understood this condition guide. Name:									