

Basic Vehicle Condition Guide

Report ID: 25,009,815


2 Version:

02 May 2025 Created:

Make: Model: Hyundai Tucson **Body Style:** SUV Year: 2022 Registration: NZQ792 Reg Expiry: 31 Oct 2025 **Odometer:** WoF Expiry: 31 Jan 2026 129,102 Kms **Good No:** 25009815 VIN: TMAJB81DMNJ102877 Next Service: 136,000kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Crack forming from stone chip in windscreen

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Battery passed test at time of inspection

| <u>Interior Comments</u> | | | | |
|--------------------------|------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Good | | | |
| Dashboard | Good | | | |

General Comments

A/c and reverse camera working at time of inspection

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

24 Apr 2025 Reuben Harvey Inspected by: Date:

Name:

| | Pass | Fail | N/A |
|------------------------------|-----------------------|---------|-----|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | \(\times \) | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | • | | |
| Coolant condition | ~ | | |
| Performance | V | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | • | | • |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | 4.0 | | mm |
| Right front | 4.0 | | mm |
| Left rear | 4.0 | | mm |
| Right rear | 4.0 | | mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | ~ | | |
| Window winder FR | V V V V V | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | | | ~ |
| Number of keys | 2 | | _ |
| Central locking | · | | |
| Remote locking | <i>y</i> | | |
| Sat. Nav. (basic test only) | | | ./ |
| Reversing camera | | | |
| neversing carriera | ' | | |

Signature: