

Report ID: 25,009,917 Version: 1 Created: 24 Apr 2025

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility		Pass	Fail	N/A
Year:	2017	Registration:	KJU107	Reg Expiry:	13 Nov 2023	Engine		I	1
WoF Expiry:	01 Nov 2024	Odometer:	315,065 Kms	Good No:	25009917	Oil level	~		
VIN:	MMAJYKL10HH001080	Next Service:	no current service history	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for any and milaage	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	· ·		
Key:	S	\neg	P D		S	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent SC 6 6 5						Operation	~		
R = rust PT = paint defect C = crack						Noise	~		
						Clutch	•		~
P = pin dent						CV joints	~		
* = decals DPT SC DP						Wheel bearings	~		
SC = stone chips						Brakes	v		
W = significant scuffs DW P D D						Performance	~		
		Note: son	ne defects & blemishe	s may not be disr	laved in the diagram	Hand Brake	~		┼──┤
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread		oftyre	25)
Paint touch ups						Left front	8	,	mm
						Right front	4		mm
						Left rear			mm
								.0	
Conditions During Body Inspection: Dry						Right rear	3.0 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare No			
onder earlage a onder bonnet inspection comments					Suspension			1	
Battery passed test at time of inspection, however battery is unsecured. Paint spilt in well side tray. Front tyres mismatched. Significant Engine oil leaks. Engine oil very dirty						Suspension performance	~		
mismatche	d. Significant Engine oil	leaks. Engine oil	very dirty			Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation		~	
						Electrical / Accessories			
Seats	Average					Head lights		~	
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		<u> </u>
Dashboa	rd Average					Wipers (front & rear)	~		<u> </u>
	Average					Window winder FL	~		ļ
Concret	ommonts					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		<u> </u>
	d in dashboard. Signific				•	Window winder RR	~		
Roof lining poor condition. Partial service history in book. Reverse camera working at time of inspection. Rh front fog light n/w. No key for canopy. No spare wheel						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanicmy Timing Chain						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Increate	d by: Reuben Harvey	Date: 24 Apr 2025							
Inspected by: Reuben Harvey Date: 24 Apr 2025									
I have read and understood this condition guide. Name:									