

Basic Vehicle Condition Guide

Report ID: 25,010,160


Version: 7

Created: 04 Jun 2025

Make: Model: KIA Sorento **Body Style:** SUV Year: 2021 Registration: NLG593 Reg Expiry: 15 Oct 2025 WoF Expiry: **Odometer: Good No:** 16 Apr 2026 106,865 Kms 25010160 VIN: KNARH81BWM5090031 Next Service: 118,000kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Stone chip spray across windscreen with 2x cracked stonechips

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | |
|--------------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Air conditioning and heating systems, along with reverse camera and navigation working at time of inspection. 1 roof rack key provided

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Gary Adams Date: 06 May 2025

Name:

| | Pass | Fail | N/A | |
|------------------------------|---------------------------------------|---------|-----|--|
| Engine | | | 1 | |
| Oil level | ~ | | | |
| Smoke & fumes | \(\times \) | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | V V | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread | depth | of tyre | es) | |
| Left front | 3. | .0 | mm | |
| Right front | 3. | .0 | mm | |
| Left rear | 3. | .0 | mm | |
| Right rear | 3. | .0 | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | > | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation 🗸 | | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | ~ | | | |
| Window winder FL | ~ | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | V V V V V V V V V V V V V V V V V V V | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 2 | | | |
| Central locking | ~ | | | |
| Remote locking | V | | | |
| Sat. Nav. (basic test only) | ' | | | |
| Reversing camera | ~ | | | |

Signature: