

Report ID: 25,010,529 3 Version: 02 Jul 2025 Created:

Make:	Mazda	Model:	Mazda2	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2016	Registration:	JWU172	Reg Expiry:	15 Jun 2026	Engine	1	I	
WoF Expiry:	07 Aug 2025	Odometer:	173,739 Kms	Good No:	25010529	Oil level	~		
VIN:	MM0DJ2HAA0W207581	Next Service:	183,738 Kms	Service History	y: Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
	SC		D* *		*	Performance	~		
Key:	Loc (L	-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission	Transmission		
D = dent R = rust PT = paint defect						Operation	~		
						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
* = decals SRSC 919 *						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Noto: come defecte % blamiches may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments							-	oftyre	(2c)
Parcel tray pin broken off. Stone chips in front screen. Potential water leak						Left front	Tyres (lowest observed tread depth of tyres)		
						Right front	5.0 mm 6.0 mm		mm
						Left rear			mm
								.0	
Conditions During Body Inspection: Dry						Right rear	4.0 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
onder earlage a onder bonnet inspection comments						Suspension			
Front brake	s getting low					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
						Electrical / Accessories			
Seats	marks					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
Consul						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Rear wiper smears. Air conditioning and heating systems working at time of inspection						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	✓		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Gary Adams						Dato: 13 May 2025			
Inspected by: Gary Adams Date: 13 May 2025									
I have read and understood this condition guide. Name:									