

Report ID: 25,026,965 1 Version: 02 Apr 2025 Created:

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility		Pass	Fail	N/A
Year:	2019	Registration:	MJD788	Reg Expiry:	17 Jun 2025	Engine			1
WoF Expiry:	17 Sep 2025	Odometer:	158,229 Kms	Good No:	25026965	Oil level	~		
VIN:	MMAJLKK10KH015428	Next Service:	161094	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged to	r an additional o	charge.	Coolant condition	~		
	SC		SC SC		SC	Performance	~		
Key:		-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	SC DIA			210	HILLS	Operation	~		
PT = paint defe	ect NP				17111	Noise	~		
C = crack					P SC	Clutch			~
P = pin dent	sc de				74116	CV joints	~		
"= decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
			P SC			Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
W/Screen chips middle x 2 ,						Left front	11.0 mm		
1						Right front	10.0 mm		mm
						Left rear	10.0 mm		mm
Conditions During Body Inspection: Dry						Right rear	10.0 mm		
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
. Suspension performance Steering performance						Suspension performance	~		
						~			
Shock absorbers						~			
Ai						Air Conditioning / Heater	eater		
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote	A					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd c i					Wipers (front & rear)	~		
	rd Good					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
CD (basic test only)									~
Number of keys							1		
Road Conditions During Test Drive: Dry							~		
Engine Timing Mechanism: Timing Chain Remote locking							~		
Sat. Nav. (Dasic test Only)									~
		ement. N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Chris Buckley Date: 02 Apr 2025									

I have read and understood this condition guide.

Name:

Signature: