

Basic Condition Guide

Report ID:	25,030,368	Version:	2
Created:	17 Nov 2025		

	ome			Created:	17 Nov 2025					
Make:	Ford	Model:	Ranger				Requires			
Body Style:	Utility	Year:	2022			OK	Attention	N/A		
Rego No.:	PAE665	Rego Expiry:	25 Jan 2026	Engine			<u> </u>			
WoF Expiry:	27 Jan 2026	Odometer:	61,761 Kms	Oil level						
Good No.:	25030368	VIN:	MPBUMFF60MX372910	Smoke & fumes		<i>\</i>				
Next Service:	75000	Service History:	Yes	Engine performance Noise		/				
Note: This report is not a warranty						/				
This report is a guide	only. Consideration is mad	e for age and mileage. Pa	Coolant co		/					
full mechanical inspe	idertaken. The vehicle has b ection prior to purchase an	Cooling pe	rformance	✓						
Key				Radiator / I	Hoses (visual)	✓				
S = Scratch R	= Rust $C=C$	Crack *= Deca	ls W = Significant scuffs	Transmiss	ion		1			
D = Dent	$\Gamma = Paint defect P = P$	Operation		/						
SC	F	P SC P SC	sc	Noise		✓				
				Clutch				~		
	(M)-			CV joints		✓				
SSC				Wheel bea	rings	✓				
330				Brakes	Brakes					
				Performan	ce	✓				
				Hand brake	e	✓				
SC	18			Tyres (lowe	Tyres (lowest observed tread depth of tyres)					
				Left front			6	6.0 mm		
			(Q)	Right front		6.0 mm				
		Left rear		3.0 mm						
S P		Right rear		3.0 mm						
Note: some defects	and blemishes may not be	e displayed in the diagra	ım	Spare		Yes				
Body Inspecti	on Comments			Suspensio	n					
R/H Cab Corne	r minor Dents ,			Suspension	n performance	/				
				Steering pe	erformance	/				
				Shock abso	orbers	/				
Conditions Dur	ing Body Inspection		Dry	Air Condit	ioning / Heater					
Under Carriag	e and Under Bonnet	Operation		/						
Oil seepage low	er engine Area,			Electrical /	Accessories					
				Head light:	5	/				
				Tail lights		/				
Interior Comm	nents			Indicators		/				
Seats:	Good		<u>. </u>	Dashboard	Dashboard warning lights					
Carpets:	Good			Wipers (front & rear)		/				
Panels:	Good	Window w	inder FL	/						
Dashboard:	Good	Window w	inder FR	/						
General Comr	1	Window w		·						
				Window w		· ·				
				Rear view r						
					c test only)	~				
Road Condition	ns During Test Drive	Dry		CD (basic to	·					
Engine Timing		Number of	-	2						
Engine Timing Mechanism Timing Chain Evidence of Cam Belt Replacement Yes No Kms					-			1		
Inspected by:				Central loc Remote loc		~				
inspected by:	Cilio Duckley			veillote io	King	•	1	1		

I have read and understood this condition guide:

Inspection Date: 06 Nov 2025

Published by:

NAME _____

Jeremy Hutchings

SIGNATURE

Sat. nav. (basic test only)

Reversing camera