

## Basic Condition Guide

Report ID:	25,030,594	Version:	1
Created:	19 Nov 2025		

Make:	Mitsubishi	Model:	Outlander	
Body Style: SUV		Year:	2022	
Rego No.: PLS537		Rego Expiry:	09 Dec 2025	
WoF Expiry:	07 Oct 2026	Odometer:	42,904 Kms	
Good No.:	25030594	VIN:	JMFXDGN0WNZ001924	
Next Service:	51000	Service History: Yes		
iagnostic testing ur	only. Consideration is made	een driven up to 50km/h	orts have not been dismantled or n from cold. The Vendor recommends or an additional charge.	
•	= Rust C = C	rack *= Decal	s W = Significant scuf	
D = Dent P	$\Gamma$ = Paint defect $P = Pi$	in dent $SC = Stor$	ne Chips	
		SC D	SC	
-				
			S	
SC A				
$ \beta$			THILL STATE OF THE	
74		1)   —	SC	
sc	IN WILL			
_			S	
	W			
	and blemishes may not be	displayed in the diagra	m	
Body inspecti	on Comments			
•				
	ring Body Inspection		Dry	
Conditions Dui				
Conditions Dur Under Carriag	e and Under Bonnet	Inspection Comm	ents	
		Inspection Comm	ents	
Under Carriag		Inspection Comm	ents	
Under Carriag		Inspection Comm	ents	
Under Carriag R/F Tyre worn o	outer Edge ,	Inspection Comm	ents	
Under Carriag R/F Tyre worn o	nents	Inspection Comm	ents	
Under Carriag R/F Tyre worn of Interior Comn Seats:	nents Good	Inspection Comm	ents	
Under Carriag R/F Tyre worn of Interior Comn Seats: Carpets:	nents Good Good	Inspection Comm	ents	
Interior Comm Seats: Carpets:	nents Good Good Good	Inspection Comm	ents	
Under Carriag R/F Tyre worn of Interior Comn Seats: Carpets:	nents Good Good Good Good	Inspection Comm	ents	

		Requires	
	OK	Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	\( \frac{1}{V} \)		
Engine performance	/		
Noise	/		
Coolant condition	/		
Cooling performance	/		
Radiator / Hoses (visual)	/		
Transmission			
Operation	/		
Noise	<b>'</b>		
Clutch			
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	/		
Hand brake	/		
Tyres (lowest observed tread of	depth of	tyres)	
Left front		Ę	5.0 mm
Right front		3	3.0 mm
Left rear		į	5.0 mm
Right rear		Ę	5.0 mm
Spare	No		
Suspension	_		
Suspension performance	/		
Steering performance	1		
Shock absorbers	1		
Air Conditioning / Heater			
Operation	<b>/</b>		
Electrical / Accessories			
Head lights	V		
Tail lights	1		
Indicators	1		
Dashboard warning lights	1		
Wipers (front & rear)	1		
Window winder FL	1		
Window winder FR	1	<u> </u>	
Window winder RL	1	<u> </u>	
Window winder RR	1		
Rear view mirrors	1	<del> </del>	
Radio (basic test only)	1	<del> </del>	
CD (basic test only)		<del> </del>	
Number of keys	2	<u> </u>	
Central locking	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	I	
Remote locking	~	-	
	1	<del>                                     </del>	
Sat. nav. (basic test only)	4		
Reversing camera			

Engine Timing N	Mechanism	Timing Chain		
Evidence of Can	n Belt Replacement	Yes	No	Kms
Inspected by:	Chris Buckley			
Published by:	Malcolm Thomas			
Inspection Date:	19 Nov 2025			
have road and u	adorstood			

Dry

have read and understood
his condition quide

Road Conditions During Test Drive