

Report ID: 25,076,444 1 Version: 29 Apr 2025 Created:

Signature:

Make:	Suzuki	Model:	Swift	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2021	Registration:	NKJ627	Reg Expiry:	05 Jul 2025	Engine	•			
WoF Expiry:	06 Apr 2026	Odometer:	64,261 Kms	Good No:	25076444	Oil level	~			
VIN:	JSAAZC83S00402701	Next Service:	80,000kms	Service Histor	y: Yes	Smoke & fumes	~			
						Performance	~			
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and ti	his can be arranged to	or an additional c	narge.	Coolant condition	~			
	SC S		P SC		P SC	Performance	~			
Key:		=		5(0)-		Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission				
D = dent R = rust SSC SSC SSC						Operation	~	 		
PT = paint defe	ect NP					Noise	~			
C = crack					SC	Clutch			~	
P = pin dent	P SC DE				241 <u>16</u>	CV joints	~			
						Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
W = Significant	W W		SC P	S	P SC	Performance	~			
Body Insr	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
body inspection comments						Tyres (lowest observed tread depth of tyres)				
						Left front	6 mm			
						Right front	e	5	mm	
						Left rear	4	ł	mm	
Conditions During Body Inspection: Wet						Right rear	5 mm			
						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	•			
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
Comoto						Tail lights	~			
Carpets	Average					Indicators	<			
Panels	Grab hand	lles need refitting	g.			Dashboard warning lights	~			
Dealahara						Wipers (front & rear)	~			
Dashboa	rd Good					Window winder FL	~			
						Window winder FR	<			
<u>General Comments</u>						Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)			~	
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~			
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspected by: Daryll Timms Date: 29 Apr 2025										

I have read and understood this condition guide.

Name: