

Report ID: 25,076,746 1 Version: 01 May 2025 Created:

Make:	Hyundai	Model:	Tucson	Body Style:	SUV		Pass	Fail	N/A
Year:	2018	Registration:	LRS268	Reg Expiry:	16 Oct 2025	Engine	I	I	I
WoF Expiry:	07 Oct 2025	Odometer:	74,445 Kms	Good No:	25076746	Oil level	~		
VIN:	TMAJ2813MJJ622321	Next Service:	76,000km	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
	S S		S* SP*		SP	Performance	~		
Key:		-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			1
R = rust	s AR			210	HIVS	Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack					P SC	Clutch			~
P = pin dent						CV joints	~		
"= decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
			P* S*		Р	Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
Tailgate moulding broken. Drivers door seal is torn.						Left front	2.5 mm		mm
						Right front	2.5 mm		mm
						Left rear	3	.5	mm
Conditions During Body Inspection: Wet						Right rear	4 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
Steering perfo						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Commonts						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
	0000					Indicators	~		
Panels	Good, LR o	door trim torn.				Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
General	omments]	Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	2		~
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
Engine Timing Mechanism: Timing Chain Remote locking							~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
						Reversing camera	~		
Inspected by: Blair Robertson Date: 01 May 2025									

I have read and understood this condition guide.

Name:

Signature: