

| Report ID: | 25,085,798  | Version: | 3 |
|------------|-------------|----------|---|
| Created:   | 24 Nov 2025 |          |   |

| Make:  | Tesla  | Model:   | Model 3                   |                              | ОК       | Requires<br>Attention | N/A    |  |
|--|--|--|---------------------------|------------------------------|----------|-----------------------|--------|--|
| Body Style:                                      | Sedan  | Year:  | 2023                      | Engine                       | OIL      | Attention             | 13/73  |  |
| Rego No.:  | PSJ936   | Rego Expiry:   | 15 Mar 2026               | Oil level                    |          |                       | 1      |  |
| WoF Expiry:                                      | 16 Mar 2026  | Odometer:  | 27,387 Kms                | Smoke & fumes                | 1        |                       | _      |  |
| Good No.:  | 25085798   | VIN:   | LRW3F7FS9NC691111         | Engine performance           | 1        |                       |        |  |
| Next Service:                                    | N/A  | Service History:                                     | Yes                       | Noise                        | 1        |                       |        |  |
| Note: This report is r                           | not a warranty   |  | Coolant condition         | +                            |          |                       |        |  |
| This report is a guide of diagnostic testing und | only. Consideration is made<br>dertaken. The vehicle has b | e for age and mileage. Pa<br>een driven up to 50km/h | Cooling performance       | · /                          |          | _                     |        |  |
| full mechanical inspe                            | ction prior to purchase and                                | d this can be arranged fo                            | Radiator / Hoses (visual) | 1                            |          |                       |        |  |
| Key  | D  |  | Transmission              |                              |          |                       |        |  |
|  | = Rust $C = C$<br>= Paint defect $P = Pi$                  |  | Operation                 | · /                          | l        |                       |        |  |
| D-Delit 11                                       |  | indent 5C = 5tol                                     | ie Cilips                 | Noise                        | 1        |                       |        |  |
|  | s  |  |                           | Clutch                       |          |                       |        |  |
|  |  |  |                           | CV joints                    |          |                       | · /    |  |
|  | $\sim$   |  | Wheel bearings            | 1                            |          |                       |        |  |
| SC \   |  | <u> </u>   |                           | Brakes                       |          |                       |        |  |
| -MI  |  |  | All                       | Performance                  | · ·      |                       | Ι      |  |
| 11   |  |  |                           | Hand brake                   | V        |                       |        |  |
|  | 6 1  |  |                           |                              |          | <u> </u>              |        |  |
|  | 19   |  |                           | Tyres (lowest observed tread | 3.5 mm   |                       |        |  |
|  |  |  |                           | Left front                   | _        |                       | 1.0 mm |  |
|  |  |  |                           | Right front                  |          |                       |        |  |
|  | S  |  |                           | Left rear                    |          |                       | 3.5 mm |  |
|  |  |  |                           | Right rear                   | 3.0 mm   |                       |        |  |
|  | nd blemishes may not be                                    | displayed in the diagra                              | m                         | Spare                        | N/A      |                       |        |  |
| Body Inspection                                  | on Comments  |  |                           | Suspension                   |          | 1                     |        |  |
|  |  |  |                           | Suspension performance       | -        |                       |        |  |
|  |  |  |                           | Steering performance         | -        |                       |        |  |
|  |  |  | <u> </u>                  | Shock absorbers              | /        |                       |        |  |
|  | ng Body Inspection   |  | Dry                       | Air Conditioning / Heater    |          | I                     | Γ      |  |
| Under Carriage                                   | e and Under Bonnet   | Inspection Comm                                      | ents                      | Operation                    | /        |                       |        |  |
|  |  |  |                           | Electrical / Accessories     |          |                       | Ι      |  |
|  |  |  |                           | Head lights                  | /        |                       |        |  |
|  |  |  |                           | Tail lights                  | /        |                       |        |  |
| Interior Comm                                    |  |  |                           | Indicators                   | /        |                       |        |  |
| Seats:   | Good   |  |                           | Dashboard warning lights     | /        |                       |        |  |
| Carpets:   | Good   |  |                           | Wipers (front & rear)        | /        |                       |        |  |
| Panels:  | Good   |  |                           | Window winder FL             | /        |                       |        |  |
| Dashboard:                                       | Good   |  |                           | Window winder FR             | /        |                       |        |  |
| General Comm                                     |  |  |                           | Window winder RL             | <b>/</b> |                       |        |  |
| Aftermarket tyre<br>1x charger - hom             |  |  | Window winder RR          | /                            |          |                       |        |  |
| ix charger - non                                 | ie charger   |  |                           | Rear view mirrors            | /        |                       |        |  |
|  |  |  |                           | Radio (basic test only)      | <b>/</b> |                       |        |  |
| Road Condition                                   | s During Test Drive  | Dry  | CD (basic test only)      |                              |          | <b>'</b>              |        |  |
| Engine Timing N                                  | Mechanism  | Unknown  | Number of keys            | 2                            |          |                       |        |  |
| Evidence of Can                                  | n Belt Replacement   | Central locking                                      | <b>/</b>                  |                              |          |                       |        |  |
| Inspected by:                                    | LukaAjitvan Woer   | den  |                           | Remote locking               | <b>'</b> |                       |        |  |
| Published by: Kate Gibson                        |  |  |                           | Sat. nav. (basic test only)  | <b>'</b> |                       |        |  |
| Inspection Date:                                 | 06 Nov 2025  |  |                           | Reversing camera             | <b>'</b> |                       |        |  |
| I have read and u                                |  |  |                           |                              |          |                       |        |  |