

## **Basic Condition Guide**

| Report ID: | 25,085,910  | Version: | 1 |
|------------|-------------|----------|---|
| Created:   | 10 Nov 2025 |          |   |

| U                      | nuel   | S Basi                    | Created: 10 Nov 2025      |  |          |           |          |  |
|------------------------|--|---------------------------|---------------------------|--|----------|-----------|----------|--|
| Make:                  | Skoda  | Model:                    | Kodiaq                    |  |          | Requires  |          |  |
| Body Style:            | SUV  | Year:                     | 2022                      | -  | OK       | Attention | N/A      |  |
| Rego No.:              | PNW487   | Rego Expiry:              | 09 Feb 2026               | Engine                                       |          |           |          |  |
| WoF Expiry:            | 16 Nov 2025  | Odometer:                 | 188,147 Kms               | Oil level                                    | /        |           |          |  |
| Good No.:              | 25085910   | VIN:                      | TMBMN9NSXN8056909         | Smoke & fumes                                | V        |           |          |  |
| Next Service:          | 190,000km  | Service History:          | No                        | Engine performance                           | <b>/</b> |           | -        |  |
| Note: This report is   |  | ,                         | Noise                     | <b>/</b>                                     |          |           |          |  |
| This report is a quide | only. Consideration is madertaken. The vehicle hab | de for age and mileage. I | Coolant condition         | <b>/</b>                                     |          |           |          |  |
| full mechanical inspe  | ection prior to purchase an                        | d this can be arranged f  | or an additional charge.  | Cooling performance                          | V        |           |          |  |
| Key                    |  |                           | Radiator / Hoses (visual) | <b>/</b>                                     |          |           |          |  |
|                        | = Rust $C = C$                                     |                           | Transmission              |  | I        |           |          |  |
| D = Dent P1            | $\Gamma = Paint defect  P = P$                     | in dent SC = Stor         | ne Chips                  | Operation                                    | <b>/</b> |           | <u> </u> |  |
|                        |  | SC P                      | P                         | Noise  | /        |           |          |  |
|                        | $\overline{}$                                      | $\top$                    |                           | Clutch                                       |          |           | <b>'</b> |  |
|                        | \ <u>@</u> -                                       |                           | SD                        | CV joints                                    | 1        |           |          |  |
| S SC /                 |  |                           |                           | Wheel bearings                               | <b>/</b> |           |          |  |
| 33C H                  |  |                           |                           | Brakes                                       |          |           |          |  |
|                        |  |                           | PSC                       | Performance                                  | <b>/</b> |           |          |  |
|                        |  |                           | P SC                      | Hand brake                                   | <b>/</b> |           |          |  |
| P SC                   | 18   |                           |                           | Tyres (lowest observed tread depth of tyres) |          |           |          |  |
|                        |  |                           |                           | Left front                                   |          |           | 2 mm     |  |
|                        |  |                           | P SC                      | Right front                                  |          | 2         | 2.5 mm   |  |
|                        |  |                           |                           | Left rear                                    | 1.5 mm   |           |          |  |
|                        |  | P                         |                           | Right rear                                   | 2.5 mm   |           |          |  |
| Note: some defects     | and blemishes may not be                           | displayed in the diagra   | ım                        | Spare  | Yes      |           |          |  |
| Body Inspection        |  |                           |                           | Suspension                                   |          |           |          |  |
| Left rear bumpe        | er moulding is broken.                             |                           |                           | Suspension performance                       | V        |           |          |  |
|                        |  |                           |                           | Steering performance                         | 1        |           |          |  |
|                        |  |                           |                           | Shock absorbers                              | 1        |           |          |  |
| Conditions Dur         | ing Body Inspection                                | Air Conditioning / Heater |                           |  |          |           |          |  |
|                        | e and Under Bonnet                                 | Inspection Comm           | Operation                 | V  |          |           |          |  |
|                        |  |                           |                           | Electrical / Accessories                     |          | <u> </u>  |          |  |
|                        |  |                           |                           | Head lights                                  | V        |           |          |  |
|                        |  |                           |                           | Tail lights                                  | 1        |           |          |  |
| Interior Comm          | nents  |                           |                           | Indicators                                   | 1        |           | -        |  |
| Seats:                 | Good   |                           |                           | Dashboard warning lights                     | 1        |           |          |  |
| Carpets:               | Good   |                           |                           | Wipers (front & rear)                        | V        |           |          |  |
| Panels:                | Good   |                           |                           | Window winder FL                             | V        |           |          |  |
| Dashboard:             |  |                           |                           | Window winder FR                             | <b>V</b> |           |          |  |
|                        | Good   |                           |                           | 1  |          |           |          |  |
| General Comn           | ileilts  |                           | Window winder RL          |  |          |           |          |  |
|                        |  |                           |                           | Window winder RR                             | 1        |           |          |  |
|                        |  |                           |                           | Rear view mirrors                            | <i>\</i> |           |          |  |
| D 16 "                 |  | D                         |                           | Radio (basic test only)                      | /        |           |          |  |
|                        | ns During Test Drive                               | Dry                       |                           | CD (basic test only)                         |          |           |          |  |
| Engine Timing          | Mechanism  | Cambelt                   |                           | Number of keys                               | 2        |           |          |  |

I have read and understood this condition guide:

Blair Robertson

Blair Robertson

10 Nov 2025

Inspected by:

Published by:

Inspection Date:

Evidence of Cam Belt Replacement

NAME

**✓** No

Yes

Kms

Central locking

Remote locking

Reversing camera

Sat. nav. (basic test only)

1

1