

Basic Vehicle Condition Guide

Report ID: 25,123,985


Version:

Created: 11 Mar 2025

Make: Model: Isuzu D-MAX **Body Style:** Utility Year: 2022 Registration: PBB879 Reg Expiry: 01 Sep 2025 **Odometer:** WoF Expiry: **Good No:** 06 Mar 2026 96,887 Kms 25123985 VIN: MPATFR40JMT008280 **Next Service:** 106000km **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Rear Wheel Drive.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Haden Brown Date: 11 Mar 2025

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	v v			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	<i>V</i>			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	d depth	of tyre	es)	
Left front		5	mm	
Right front	8		mm	
Left rear		4	mm	
Right rear	3		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	<i>v</i>			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	V			
Dashboard warning lights	~			
Wipers (front & rear)	<i>'</i>			
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	3	-		
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			~	
Reversing camera	~			

I have read and understood this condition guide.

Name:

Signature: