

Basic Vehicle Condition Guide

Report ID: 25,125,503


Version:

Created: 07 Apr 2025

Make: Model: Hyundai lload **Body Style:** Van Year: 2019 Registration: MFR567 Reg Expiry: 26 Jun 2025 **Odometer:** WoF Expiry: **Good No:** 04 Jul 2025 144,555 Kms 25125503 VIN: KMFWBX7KLLU090163 Next Service: 159500km **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Windscreen molding is missing both sides.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | |
|--------------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Rear Wheel Drive.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Haden Brown Date: 07 Apr 2025

Name:

| | Pass | Fail | N/A |
|------------------------------|--|---------|----------|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | \(\times \) | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | • | • | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | • | • | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | \(\times \) | | |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed treac | d depth | of tyre | es) |
| Left front | 7 | 7 | mm |
| Right front | 7 | 7 | mm |
| Left rear | 7 | 7 | mm |
| Right rear | - | 7 | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | V | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | ļ | | |
| Operation | ~ | | |
| Electrical / Accessories | | | 1 |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | \(\times \) \(\t | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | | | ~ |
| Window winder RR | | | V |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | <i>'</i> | | |
| CD (basic test only) | ~ | | |
| Number of keys | 2 | | |
| Central locking | · | | |
| Remote locking | <i>y</i> | | |
| Sat. Nav. (basic test only) | | | - |
| Reversing camera | V | | - |
| neversing carriera | | | |

Signature: