



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	25,133,119
Version:	1
Created:	29 Dec 2023

Make:	Honda	Body Style:	
Model:	Shuttle	VIN:	
Year:	2015	Odometer:	99,848 Kms
Road Conditions During Test Drive:	Dry		

Electrical			Cooling System			Exterior		
1	Battery	<input checked="" type="checkbox"/>	30	Fuel Flap Release	<input checked="" type="checkbox"/>	78	Under Carriage	Good
2	Headlights	<input checked="" type="checkbox"/>	31	Reversing Camera	<input checked="" type="checkbox"/>	79	Sun Roof Operation	<input type="checkbox"/>
3	Tail Lights	<input checked="" type="checkbox"/>	32	USB Port	<input type="checkbox"/>	80	Front Windscreen (no chips)	Good
4	High Stop Light	<input checked="" type="checkbox"/>	33	Window Lock Switch	<input checked="" type="checkbox"/>	81	Back Windscreen (no chips)	Good
5	Front Right Indicators	<input checked="" type="checkbox"/>	Transmission and Drive			82	Side Windows (no chips)	Good
6	Front Left Indicators	<input checked="" type="checkbox"/>	34	Operation	<input checked="" type="checkbox"/>	83	Front Wiper Blades	Good
7	Rear Right Indicators	<input checked="" type="checkbox"/>	35	Noise	<input checked="" type="checkbox"/>	84	Rear Wiper Blade	Good
8	Rear Left Indicators	<input checked="" type="checkbox"/>	36	Clutch	<input type="checkbox"/>	85	R/H Mirror	Good
9	Reversing Lights	<input checked="" type="checkbox"/>	37	CV Joints	<input checked="" type="checkbox"/>	86	L/H Mirror	Good
10	Rear Reflectors	<input checked="" type="checkbox"/>	38	Wheel Bearing	<input checked="" type="checkbox"/>	87	L/F Guard	Good
11	Hazard Lights	<input checked="" type="checkbox"/>	39	Wheel Balance	<input checked="" type="checkbox"/>	88	R/F Guard	Good
12	Courtesy Lights	<input type="checkbox"/>	40	Gearbox (Manual)	<input type="checkbox"/>	89	L/H Doors	Good
13	Dashboard Lights	<input checked="" type="checkbox"/>	41	Engine Timing	Timing Chain	90	R/H Doors	Good
14	Dashboard Dimmer Switch	<input checked="" type="checkbox"/>	42	Evidence of Cam Belt Replacement	Not Applicable	91	L/H Sill	Good
15	Number Plate Light	<input checked="" type="checkbox"/>	43	Replaced at (odometer reading)		92	R/H Sill	Good
16	Dashboard Warning Lights	<input checked="" type="checkbox"/>	Brakes			93	Boot/Tail Gate	Good
17	Speedo	<input checked="" type="checkbox"/>	44	Front Brakes	<input checked="" type="checkbox"/>	94	Front Bumper	Good
18	Odometer	<input checked="" type="checkbox"/>	45	Rear Brakes	<input checked="" type="checkbox"/>	95	Rear Bumper	Good
19	Rev Counter	<input type="checkbox"/>	46	Handbrake	<input checked="" type="checkbox"/>	96	Roof	Good
20	Fuel Gauge	<input checked="" type="checkbox"/>	Keys and Locking			97	Bonnet	Good
21	Wipers Front/Rear	<input checked="" type="checkbox"/>	47	Central Locking	<input checked="" type="checkbox"/>	98	Fuel Cap	<input checked="" type="checkbox"/>
22	Window Opener FL	<input checked="" type="checkbox"/>	48	Remote Locking	<input checked="" type="checkbox"/>	99	Mud Flaps	<input checked="" type="checkbox"/>
23	Window Opener FR	<input checked="" type="checkbox"/>	49	Number of Keys	2	100	WOF	<input checked="" type="checkbox"/>
24	Window Opener RL	<input checked="" type="checkbox"/>	Engine			Turners Certification Key: ✓ = Pass ✗ = Fail • = Not applicable for this vehicle		
25	Window Opener RR	<input checked="" type="checkbox"/>	50	Oil Level	<input checked="" type="checkbox"/>			
26	Rear View Mirrors	<input checked="" type="checkbox"/>	51	Smokes and Fumes	<input checked="" type="checkbox"/>			
27	Radio (Basic Test Only)	<input checked="" type="checkbox"/>	52	Performance	<input checked="" type="checkbox"/>			
28	CD (Basic Test Only)	<input checked="" type="checkbox"/>	53	Noise	<input checked="" type="checkbox"/>			
29	Boot Open Switch	<input checked="" type="checkbox"/>	54	Starter Motor	<input checked="" type="checkbox"/>			
			55	Coolant Condition	<input checked="" type="checkbox"/>			
			56	Performance	<input checked="" type="checkbox"/>			
			57	Radiator/Hoses (visual)	<input checked="" type="checkbox"/>			
			Suspension					
			58	Suspension Performance	<input checked="" type="checkbox"/>			
			59	Steering Performance	<input checked="" type="checkbox"/>			
			60	Shock Absorbers	<input checked="" type="checkbox"/>			
			Wheels and Tyres					
			61	Left Front	4.5 mm			
			62	Right Front	4.5 mm			
			63	Left Rear	6 mm			
			64	Right Rear	6 mm			
			65	Spare	N/A			
			66	Tools	<input checked="" type="checkbox"/>			
			Interior					
			67	AC Operation	<input checked="" type="checkbox"/>			
			68	Heater Fan	<input checked="" type="checkbox"/>			
			69	Seatbelts	<input checked="" type="checkbox"/>			
			70	Horn	<input checked="" type="checkbox"/>			
			71	Seat Heaters	<input type="checkbox"/>			
			72	Sun Visors	<input checked="" type="checkbox"/>			
			73	Sun Visors Lights/Mirrors	<input checked="" type="checkbox"/>			
			74	Seats	Good			
			75	Carpets	Good			
			76	Panels	Good			
			77	Dashboard	Good			

Inspected by:	Blair Robertson	Date:	29 Dec 2023
I have read and understood this condition guide:			
Name:		Signature:	