



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	25,133,347
Version:	2
Created:	14 May 2024

Make:	Mitsubishi	Body Style:	SUV
Model:	Outlander	VIN:	7AT0CJ3MX24006339
Year:	2013	Odometer:	79,431 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good																																																																																																																																																	
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good																																																																																																																																																	
2	Headlights	✓	32	USB Port	✓	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good																																																																																																																																																	
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓	83	Front Wiper Blades	Good																																																																																																																																																		
4	High Stop Light	✓	Transmission and Drive		59	Steering Performance	✓	60	Shock Absorbers	✓	84	Rear Wiper Blade	Good																																																																																																																																																		
5	Front Right Indicators	✓	34	Operation	✓	Wheels and Tyres		61	Left Front	4.5	mm	85	R/H Mirror	Good																																																																																																																																																	
6	Front Left Indicators	✓	35	Noise	✓	62	Right Front	4.5	mm	63	Left Rear	5.0	mm	86	L/H Mirror	Good																																																																																																																																															
7	Rear Right Indicators	✓	36	Clutch	•	64	Right Rear	4.5	mm	65	Spare	N/A	66	Tools	✓	87	L/F Guard	Good																																																																																																																																													
8	Rear Left Indicators	✓	37	CV Joints	✓	Interior		67	AC Operation	✓	68	Heater Fan	✓	69	Seatbelts	✓	70	Horn	✓	71	Seat Heaters	✓	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good																																																																																																																							
9	Reversing Lights	✓	38	Wheel Bearing	✓	61	Left Front	4.5	mm	62	Right Front	4.5	mm	63	Left Rear	5.0	mm	64	Right Rear	4.5	mm	65	Spare	N/A	66	Tools	✓	67	AC Operation	✓	68	Heater Fan	✓	69	Seatbelts	✓	70	Horn	✓	71	Seat Heaters	✓	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good																																																																																																			
10	Rear Reflectors	✓	39	Wheel Balance	✓	62	Right Front	4.5	mm	63	Left Rear	5.0	mm	64	Right Rear	4.5	mm	65	Spare	N/A	66	Tools	✓	67	AC Operation	✓	68	Heater Fan	✓	69	Seatbelts	✓	70	Horn	✓	71	Seat Heaters	✓	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good																																																																																																							
11	Hazard Lights	✓	40	Gearbox (Manual)	•	65	Spare	N/A	66	Tools	✓	67	AC Operation	✓	68	Heater Fan	✓	69	Seatbelts	✓	70	Horn	✓	71	Seat Heaters	✓	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good																																																																																																																			
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	66	Tools	✓	67	AC Operation	✓	68	Heater Fan	✓	69	Seatbelts	✓	70	Horn	✓	71	Seat Heaters	✓	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good																																																																																																																						
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	67	AC Operation	✓	68	Heater Fan	✓	69	Seatbelts	✓	70	Horn	✓	71	Seat Heaters	✓	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good																																																																																																																									
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		68	Heater Fan	✓	69	Seatbelts	✓	70	Horn	✓	71	Seat Heaters	✓	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good																																																																																																																												
15	Number Plate Light	✓	Brakes		44	Front Brakes	✓	69	Seatbelts	✓	70	Horn	✓	71	Seat Heaters	✓	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good																																																																																																																													
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	70	Horn	✓	71	Seat Heaters	✓	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good	78	Under Carriage	Good	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good	85	R/H Mirror	Good	86	L/H Mirror	Good	87	L/F Guard	Good	88	R/F Guard	Good	89	L/H Doors	Good	90	R/H Doors	Good	91	L/H Sill	Good	92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓																																																													
17	Speedo	✓	45	Rear Brakes	✓	71	Seat Heaters	✓	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good	78	Under Carriage	Good	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good	85	R/H Mirror	Good	86	L/H Mirror	Good	87	L/F Guard	Good	88	R/F Guard	Good	89	L/H Doors	Good	90	R/H Doors	Good	91	L/H Sill	Good	92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓																																																																
18	Odometer	✓	46	Handbrake	✓	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good	78	Under Carriage	Good	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good	85	R/H Mirror	Good	86	L/H Mirror	Good	87	L/F Guard	Good	88	R/F Guard	Good	89	L/H Doors	Good	90	R/H Doors	Good	91	L/H Sill	Good	92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓																																																																			
19	Rev Counter	✓	Keys and Locking		47	Central Locking	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good	78	Under Carriage	Good	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good	85	R/H Mirror	Good	86	L/H Mirror	Good	87	L/F Guard	Good	88	R/F Guard	Good	89	L/H Doors	Good	90	R/H Doors	Good	91	L/H Sill	Good	92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓																																																																				
20	Fuel Gauge	✓	48	Remote Locking	✓	74	Seats	Good	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good	78	Under Carriage	Good	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good	85	R/H Mirror	Good	86	L/H Mirror	Good	87	L/F Guard	Good	88	R/F Guard	Good	89	L/H Doors	Good	90	R/H Doors	Good	91	L/H Sill	Good	92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓																																																																									
21	Wipers Front/Rear	✓	49	Number of Keys	2	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good	78	Under Carriage	Good	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good	85	R/H Mirror	Good	86	L/H Mirror	Good	87	L/F Guard	Good	88	R/F Guard	Good	89	L/H Doors	Good	90	R/H Doors	Good	91	L/H Sill	Good	92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓																																																																												
22	Window Opener FL	✓	Engine		50	Oil Level	✓	76	Panels	Good	77	Dashboard	Good	78	Under Carriage	Good	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good	85	R/H Mirror	Good	86	L/H Mirror	Good	87	L/F Guard	Good	88	R/F Guard	Good	89	L/H Doors	Good	90	R/H Doors	Good	91	L/H Sill	Good	92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓																																																																													
23	Window Opener FR	✓	50	Oil Level	✓	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓	55	Coolant Condition	✓	56	Performance	✓	57	Radiator/Hoses (visual)	✓	58	Suspension Performance	✓	59	Steering Performance	✓	60	Shock Absorbers	✓	61	Left Front	4.5	mm	62	Right Front	4.5	mm	63	Left Rear	5.0	mm	64	Right Rear	4.5	mm	65	Spare	N/A	66	Tools	✓	67	AC Operation	✓	68	Heater Fan	✓	69	Seatbelts	✓	70	Horn	✓	71	Seat Heaters	✓	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good	78	Under Carriage	Good	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good	85	R/H Mirror	Good	86	L/H Mirror	Good	87	L/F Guard	Good	88	R/F Guard	Good	89	L/H Doors	Good	90	R/H Doors	Good	91	L/H Sill	Good	92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓
24	Window Opener RL	✓	50	Oil Level	✓	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓	55	Coolant Condition	✓	56	Performance	✓	57	Radiator/Hoses (visual)	✓	58	Suspension Performance	✓	59	Steering Performance	✓	60	Shock Absorbers	✓	61	Left Front	4.5	mm	62	Right Front	4.5	mm	63	Left Rear	5.0	mm	64	Right Rear	4.5	mm	65	Spare	N/A	66	Tools	✓	67	AC Operation	✓	68	Heater Fan	✓	69	Seatbelts	✓	70	Horn	✓	71	Seat Heaters	✓	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good	78	Under Carriage	Good	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good	85	R/H Mirror	Good	86	L/H Mirror	Good	87	L/F Guard	Good	88	R/F Guard	Good	89	L/H Doors	Good	90	R/H Doors	Good	91	L/H Sill	Good	92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓
25	Window Opener RR	✓	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓	55	Coolant Condition	✓	56	Performance	✓	57	Radiator/Hoses (visual)	✓	58	Suspension Performance	✓	59	Steering Performance	✓	60	Shock Absorbers	✓	61	Left Front	4.5	mm	62	Right Front	4.5	mm	63	Left Rear	5.0	mm	64	Right Rear	4.5	mm	65	Spare	N/A	66	Tools	✓	67	AC Operation	✓	68	Heater Fan	✓	69	Seatbelts	✓	70	Horn	✓	71	Seat Heaters	✓	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good	78	Under Carriage	Good	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good	85	R/H Mirror	Good	86	L/H Mirror	Good	87	L/F Guard	Good	88	R/F Guard	Good	89	L/H Doors	Good	90	R/H Doors	Good	91	L/H Sill	Good	92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓			
26	Rear View Mirrors	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓	55	Coolant Condition	✓	56	Performance	✓	57	Radiator/Hoses (visual)	✓	58	Suspension Performance	✓	59	Steering Performance	✓	60	Shock Absorbers	✓	61	Left Front	4.5	mm	62	Right Front	4.5	mm	63	Left Rear	5.0	mm	64	Right Rear	4.5	mm	65	Spare	N/A	66	Tools	✓	67	AC Operation	✓	68	Heater Fan	✓	69	Seatbelts	✓	70	Horn	✓	71	Seat Heaters	✓	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good	78	Under Carriage	Good	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good	85	R/H Mirror	Good	86	L/H Mirror	Good	87	L/F Guard	Good	88	R/F Guard	Good	89	L/H Doors	Good	90	R/H Doors	Good	91	L/H Sill	Good	92	R/H Sill	Good	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓	100	WOF	✓						
27	Radio (Basic Test Only)	✓	53	Noise	✓	54	Starter Motor	✓	55	Coolant Condition	✓	56	Performance	✓	57	Radiator/Hoses (visual)	✓	58	Suspension Performance	✓	59	Steering Performance	✓	60	Shock Absorbers	✓																																																																																																																																					

Inspected by:	Dale Dryden	Date:	11 Jan 2024
I have read and understood this condition guide:			
Name:		Signature:	