



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	25,133,375
Version:	1
Created:	17 Jan 2024

Make:	Mercedes-Benz	Body Style:	Hatchback
Model:	B180	VIN:	WDD2462422J136427
Year:	2013	Odometer:	35,940 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good						
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good						
2	Headlights	✓	32	USB Port	✓	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good						
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓	83	Front Wiper Blades	Good							
4	High Stop Light	✓	Transmission and Drive		59	Steering Performance	✓	60	Shock Absorbers	✓	84	Rear Wiper Blade	Good							
5	Front Right Indicators	✓	34	Operation	✓	Wheels and Tyres		61	Left Front	7	mm	85	R/H Mirror	Good						
6	Front Left Indicators	✓	35	Noise	✓	62	Right Front	7	mm	63	Left Rear	7	mm	86	L/H Mirror	Good				
7	Rear Right Indicators	✓	36	Clutch	•	64	Right Rear	7	mm	65	Spare	N/A	66	Tools	✓	87	L/F Guard	Good		
8	Rear Left Indicators	✓	37	CV Joints	✓	Interior		67	AC Operation	✓	68	Heater Fan	✓	69	Seatbelts	✓	88	R/F Guard	Good	
9	Reversing Lights	✓	38	Wheel Bearing	✓	70	Horn	✓	71	Seat Heaters	•	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	89	L/H Doors	Good
10	Rear Reflectors	✓	39	Wheel Balance	✓	74	Seats	Good	75	Carpets	Good	76	Panels	Good	77	Dashboard	Good	90	R/H Doors	Good
11	Hazard Lights	✓	40	Gearbox (Manual)	•							91	L/H Sill	Good	92	R/H Sill	Good	93	Boot/Tail Gate	Good
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain							94	Front Bumper	Good	95	Rear Bumper	Good	96	Roof	Good
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable							97	Bonnet	Good	98	Fuel Cap	✓	99	Mud Flaps	✓
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)								100	WOF	✓						
15	Number Plate Light	✓	Brakes		44	Front Brakes	✓ <td colspan="2"></td> <td colspan="2"></td> <td colspan="4"></td>													
16	Dashboard Warning Lights	✓	45	Rear Brakes	✓ <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="4"></td>															
17	Speedo	✓	46	Handbrake	✓ <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="4"></td>															
18	Odometer	✓	Keys and Locking		47	Central Locking	✓ <td colspan="2"></td> <td colspan="2"></td> <td colspan="4"></td>													
19	Rev Counter	✓	48	Remote Locking	✓ <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="4"></td>															
20	Fuel Gauge	✓	49	Number of Keys	1															
21	Wipers Front/Rear	✓	Engine		50	Oil Level	✓ <td colspan="2"></td> <td colspan="2"></td> <td colspan="4"></td>													
22	Window Opener FL	✓	51	Smokes and Fumes	✓ <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="4"></td>															
23	Window Opener FR	✓	52	Performance	✓ <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="4"></td>															
24	Window Opener RL	✓	53	Noise	✓ <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="4"></td>															
25	Window Opener RR	✓	54	Starter Motor	✓ <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="4"></td>															
26	Rear View Mirrors	✓																		
27	Radio (Basic Test Only)	✓																		
28	CD (Basic Test Only)	✓																		
29	Boot Open Switch	✓																		

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Lukin Koveskali	Date:	17 Jan 2024
I have read and understood this condition guide:			
Name:		Signature:	