

I have read and understood this condition guide.

Report ID: 25,143,192 Version: 3 09 Jan 2024 Created:

Signature:

Make:	Hyundai	Model:	Santa FE	Body Style:	SUV		Pass	Fail	N/A
Year:	2013	Registration:	HDW189	Reg Expiry:	19 Nov 2024	Engine	•		
WoF Expiry:	28 Dec 2024	Odometer:	208,292 Kms	Good No:	25143192	Oil level	~		
VIN:	KMHST81XSEU229404	Next Service:	215000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechai		purchase and ti	lis can be allanged ic		inarge.	Coolant condition	~		
	W	\sim	SC SC		D	Performance	~		
Key: S = scratch						Radiator / Hoses (visual)	Radiator / Hoses (visual) 🖌		
D = dent						Transmission			
D = dent R = rust PT = paint defect R SC						Operation	~		
						Noise	~		
C = crack				\square	R SC	Clutch			~
P = pin dent	RSC DIC				~848	CV joints	~		
* = decals RSC SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
	S W	\sim	SC S	W	S	Performance	~		
Body Ins	pection Comments	Note: son	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
Holes in bumper						Tyres (lowest observed tread depth of tyres)			
						Left front	6	.0	mm
						Right front	6	.0	mm
r						Left rear	3.	.5	mm
Conditions During Body Inspection: Dry						Right rear 4.0 mm			mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Good						Electrical / Accessories	1		
Seats	0000					Head lights	~		
Carpets	Average					Tail lights	~		
<u> </u>	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
General (omments					Window winder FR	~		
General Comments 2013 Hyundai Santa FE DM 4WD 5DR SUV (2.2) Auto Diesel						Window winder RL	~		
					Window winder RR	~			
Drivers window switch damaged Holes along dashboard					Rear view mirrors	~			
Key is rough but operating						Radio (basic test only)	~		
Drivers mat has hole Holes in bumper						CD (basic test only)			
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	V 		
Engine Timing Mechanism: Timing Chain						Remote locking	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
						Reversing camera			~
Inspected by: Jaykib Collins Date: 29 Nov 2023									

Name: