

Report ID: 25,145,453 Version: 2 21 Feb 2024 Created:

Make:	Mazda	Model:	Axela	Body Style:		Pass	Fail	N/A
Year:	2015	<b>Registration:</b>		Reg Expiry:	Engine	1	I	1
WoF Expiry:	10 Feb 2025	Odometer:	45,975 Kms	Good No: 25145453	Oil level	~		1
VIN:		Next Service:	55,972 km	Service History: No	Smoke & fumes	~		
					Performance	~		
	port is not a warranty		for ago and milaago	Parts have not been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional charge.	Coolant condition	~		
					Performance	~		
Key:		-0			Radiator / Hoses (visual)	~		+
S = scratch					Transmission			
					Operation	~		1
R = rust PT = paint defe					Noise	~		
C = crack					Clutch	•		~
P = pin dent	Hto				CV joints	~		
* = decals	- BIK				Wheel bearings	~		<del> </del>
SC = stone chips					Brakes			L
W = significant scuffs					Performance	~		<u> </u>
		Noto: com	L defects & blomishes	may not be displayed in the diagram		-		──
<u>Body Insp</u>	pection Comments		le délects & biemisnes	may not be displayed in the diagram	Hand Brake			>
					<b>Tyres</b> (lowest observed tread depth of tyres)			
					Left front		5	mm
					Right front		5	mm
					Left rear		8 mm	
Conditions During Body Inspection: Dry					Right rear	8 mm		
Under Comiene & Under Deservation Comments					Spare			
Under Carriage & Under Bonnet Inspection Comments					Suspension			
fwd					Suspension performance	~		<u> </u>
					Steering performance	~		<u> </u>
					Shock absorbers	~		
					Air Conditioning / Heater			
lu ta via v					Operation	~		
Interior Comments					Electrical / Accessories			
Seats	Good				Head lights	~		
Carpota	Good				Tail lights	~		
Carpets					Indicators	~		
Panels	Good				Dashboard warning lights		~	
	Good				Wipers (front & rear)	~		
Dashboa	ra				Window winder FL	~		
					Window winder FR	~		
<u>General C</u>	<u>Comments</u>				Window winder RL	~		
					Window winder RR	~		
					Rear view mirrors	~		1
					Radio (basic test only)	~		1
					CD (basic test only)			~
					Number of keys	2	I	1
Road Conditions During Test Drive: Dry					Central locking	~		
					Remote locking	~		1
Engine Tir	ming Mechanism:	Timing (	Chain		Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:	Reversing camera	~		† ·
I						1	1	
Inspected by: Allan Young Date: 21 Feb 2024								

I have read and understood this condition guide.

Name: .....

Signature: .....