

Basic Vehicle Condition Guide

Report ID: 25,145,476

Version: 3


Created: 28 Feb 2024

Make: Model: Mazda Demio **Body Style:** Year: 2014 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 23 Feb 2025 85,637 Kms

25145476 **Next Service:** VIN: 95,000 km Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

FWD.

PNP.

| Interior Comments | | | |
|-------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Front bumper missing lower grill.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Todd Cullum 28 Feb 2024 Inspected by:

| | Pass | Fail | N/A | |
|---|--|---------|----------|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | \(\triangle \) | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread | depth | of tyre | <u> </u> | |
| Left front | | 5 | mm | |
| Right front | 5 | | mm | |
| Left rear | 4 | | mm | |
| Right rear | 4 | | mm | |
| Spare | | No | | |
| Suspension | ı | ı | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | 1 | I | | |
| Operation | ' | | | |
| Electrical / Accessories | | | | |
| Head lights | • | | | |
| Tail lights | ~ | | | |
| Indicators | <i>V</i> | | | |
| Dashboard warning lights | • | | | |
| Wipers (front & rear) | • | | | |
| Window winder FL | \(\times \) \(\t | | | |
| Window winder FR | | | | |
| Window winder RL | <i>V</i> | | | |
| Window winder RR | | | | |
| Rear view mirrors | \(\times \) | | | |
| Radio (basic test only) | | | | |
| CD (basic test only) | 1 | | | |
| Number of keys | 1 | | | |
| Central locking Remote locking | • | | | |
| <u> </u> | | | | |
| Sat. Nav. (basic test only) Reversing camera | | | | |
| neversing camera | | | | |

I have read and understood this condition guide.

Name:

Signature: