

Report ID: 25,145,509 Version: 3 27 Feb 2024 Created:

Make:	Mitsubishi	Model:	Outlander	Body Style:	Wagon		Pass	Fail	N/A
Year:	2014	Registration:	Catanaci	Reg Expiry:	magon	Engine			
	2014 21 Feb 2025	Odometer:	93,413 Kms	Good No:	25145509	Oil level	~		
VIN:	7AT0CJ3MX24011896			Service Histor		Smoke & fumes	~		
	781003300824011890		105,000 km		y . No	Performance	~		
	port is not a warranty					Noise	-		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends									
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition Performance	~		
Key:							~		
S = scratch	R	(0)	<u>A</u>	10/5	~	Radiator / Hoses (visual)	~		
D = dent						Transmission			
R = rust	MIP			\sim	SHUK	Operation	~		
PT = paint def	ect 🛛					Noise	~		
C = crack	III					Clutch			~
P = pin dent * = decals	dic			SI_	THE	CV joints	~		
SC = stone chips						Wheel bearings			
W = significant scuffs						Brakes			
						Performance	~		
Body Ins	pection Comments	Note: son	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	7.0 mi		mm
						Right front	7.0 mm		mm
						Left rear	8	.0	mm
Conditions During Body Inspection: Dry						Right rear	8.0 mn		mm
						Spare	No		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
4WD.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	V		
<u></u>	Good					Tail lights	~		
Carpets	0000					Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Card					Wipers (front & rear)	~		
Dashboa	ord Good					Window winder FL	~		
	1					Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		L
							2 V		
Road Conditions During Test Drive: Dry Central locking Remote locking Remote locking							~		
Engine Ti	ming Mechanism:	Timing	Chain			-			
Engine mining mechanism. Imining chain Sat. Nav. (basic test only) Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera							~		~
Inspected by: Marlon Espena Date: 26 Feb 2024									

I have read and understood this condition guide.

Name:

Signature: