

Basic Vehicle Condition Guide

Report ID: 25,145,584

Version: 1

Created: 05 Mar 2024


Make:MazdaModel:AxelaBody Style:Year:2014Registration:Reg Expiry:

 WoF Expiry:
 01 Mar 2025
 Odometer:
 58,966 Kms
 Good No:
 25145584

 VIN:
 Next Service:
 68,962 km
 Service History:
 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

FWD

| Interior Comments | | | |
|-------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

| | _ |
|---------|----------|
| General | Comments |

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Allan Young

Name:

| | | , | | | | |
|--|---------------------------------------|------|-----|--|--|--|
| | Pass | Fail | N/A | | | |
| Engine | | | | | | |
| Oil level | ~ | | | | | |
| Smoke & fumes | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | | | | |
| Performance | > | | | | | |
| Noise | ~ | | | | | |
| Cooling System | | | | | | |
| Coolant condition | / | | | | | |
| Performance | ~ | | | | | |
| Radiator / Hoses (visual) | ~ | | | | | |
| Transmission | | | | | | |
| Operation | ~ | | | | | |
| Noise | > | | | | | |
| Clutch | | | ~ | | | |
| CV joints | ~ | | | | | |
| Wheel bearings | ~ | | | | | |
| Brakes | | | | | | |
| Performance | ~ | | | | | |
| Hand Brake | ~ | | | | | |
| Tyres (lowest observed tread depth of tyres) | | | | | | |
| Left front | | 4 | mm | | | |
| Right front | | 4 | mm | | | |
| Left rear | | 4 | mm | | | |
| Right rear | | 4 | mm | | | |
| Spare | | N/A | | | | |
| Suspension | | | | | | |
| Suspension performance | ~ | | | | | |
| Steering performance | ~ | | | | | |
| Shock absorbers | ~ | | | | | |
| Air Conditioning / Heater | | | | | | |
| Operation | ~ | | | | | |
| Electrical / Accessories | | 1 | | | | |
| Head lights | ~ | | | | | |
| Tail lights | ~ | | | | | |
| Indicators | | | | | | |
| Dashboard warning lights | ~ | | | | | |
| Wipers (front & rear) | \(\times \) | | | | | |
| Window winder FL | ~ | | | | | |
| Window winder FR | ~ | | | | | |
| Window winder RL | ~ | | | | | |
| Window winder RR | ~ | | | | | |
| Rear view mirrors | ~ | | | | | |
| Radio (basic test only) | / | | | | | |
| CD (basic test only) | ~ | | | | | |
| Number of keys | 2 | 1 | | | | |
| Central locking | ~ | | | | | |
| Remote locking | ~ | | | | | |
| Sat. Nav. (basic test only) | | | ~ | | | |
| Reversing camera | ' | | | | | |
| | | • | | | | |

05 Mar 2024

Signature:

Date: