

Report ID: 25,145,606 Version: 2 09 Feb 2024 Created:

Make:	Subaru	Model:	Impreza	Body Style:			Pass	Fail	N/A
Year:	2013	<b>Registration:</b>		Reg Expiry:		Engine			
WoF Expiry:	08 Feb 2025	Odometer:	30,073 Kms	Good No: 2	25145606	Oil level	~		
VIN:		Next Service:	40,070 km	Service History:	No	Smoke & fumes	r		
						Performance	~		
	port is not a warranty		for age and mileage	Parts have not h	een dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	nical inspection prior to	purchase and th	nis can be arranged fo	or an additional cha	arge.	Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	- HE					Operation	~		
R = rust PT = paint def	act NP			$\prod$	HH	Noise	~		
C = crack						Clutch			~
P = pin dent	H			$ \rangle$	411	CV joints	~		
* = decals	616			The	ETTP-	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: som	ne defects & blemishes	may not be displa	aved in the diagram	Hand Brake	~		
Body Inst	pection Comments	5		indy not be displa	iyea in the alagram		-	oftyre	
					Tyres (lowest observed tread depth of tyres)   Left front 8 mm				
						Right front Left rear		3	mm
								3	mm
Conditions During Body Inspection: Dry									mm
Under Carriage & Under Bonnet Inspection Comments						Spare N/A			
F w d	inage a onder boi	meenspeede	<u>eominents</u>			Suspension			
I WU						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation			
Good						Electrical / Accessories			
Seats	0000					Head lights	~		
Carpets	Good					Tail lights	~		
	Cood					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good Good					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
,						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	cement: N	lot Applicable	Kms:		Reversing camera	~		
							24		-
Inspected by: Allan Young Date: 09 Feb 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....