

Report ID: 25,173,356 Version: 2 23 Apr 2024 Created:

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2015	Registration:	JGQ213	Reg Expiry:	26 Feb 2024	Engine	1		
WoF Expiry:	08 Feb 2024	Odometer:	149,191 Kms	Good No:	25173356	Oil level	~		
VIN:	MNTCB4D23A000719	Next Service:	151,000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
	SC W		P SC W P SC		S SC W	Performance	~		
Key:	ISC W	-0	PSCW PSC		SSC W	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SSC W						Operation	~		
PT = paint defect C = crack						Noise	~		
						Clutch			~
P = pin dent						CV joints	~		
"= decais						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S W W S W P SC W						Performance	~		
Body Incr	oction Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Stone ching in winderson (not in C)(A)					Tyres (lowest observed tread	d depth	of tyre	s)	
Stone chips in windscreen (not in C.V.A)					Left front 3 mm				
						Right front	4	Ļ	mm
						Left rear	7	,	mm
Conditions During Body Inspection: Dry						Right rear	7 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
4wd						Suspension performance	~		
New Chassis & rear differential fitted						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
Performance chip fitted Drivers seat base foam collapsed						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
			-			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Andre Dichardson									
Inspected by: Andre Richardson Date: 23 Apr 2024									

I have read and understood this condition guide.

Name:

Signature: