

Report ID: 25,478,095 Version: 5 06 Jun 2024 Created:

Make:	lsuzu	Model:	D-MAX	Body Style:	Utility		Pass	Fail	N/A
Year:	2023	<b>Registration:</b>	PQU296	<b>Reg Expiry:</b>	16 Oct 2024	Engine			
WoF Expiry:	10 Feb 2026	Odometer:	9,411 Kms	Good No:	25478095	Oil level	~		
VIN:	MPATFR40JPT000199	Next Service:	15,000 km	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
						Performance	V		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust				215	HIV	Operation	~		
PT = paint defe				$\left[ \left( \right) \right]$		Noise	r		
C = crack						Clutch			~
P = pin dent	HID				74114	CV joints	~		
* = decals	- Alt			The second		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w = significan						Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	d depth	of tyre	es)
						Left front	Left front 7.0		
						Right front	7	.0	mm
						Left rear		.0	mm
						Right rear	7	7.0 mm	
Conditions During Body inspection. Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Rear wheel	drive					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	V		
						Air Conditioning / Heater	I		
						Operation	V		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	V		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	1					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		L
Road Conditions During Test Drive: Dry Central loc							~		
		. 51170.				Remote locking	~		
Engine Tir	ming Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
L									1
Inspected by: Andre Richardson Date: 15 Mar 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....