



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	25,478,373
Version:	1
Created:	16 Jan 2024

Make:	Toyota	Body Style:	Wagon
Model:	Corolla	VIN:	7AT0H607X24026236
Year:	2016	Odometer:	93,527 Kms
Road Conditions During Test Drive:	Wet		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good						
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation		•								
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	80	Front Windscreen (no chips)	Good	81	Back Windscreen (no chips)	Good						
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>82</td> <td>Side Windows (no chips)</td> <td>Good</td> <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	82	Side Windows (no chips)	Good	83	Front Wiper Blades	Good				
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td><td>85</td><td>R/H Mirror</td><td>Good</td></th>	59	Steering Performance	✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	84	Rear Wiper Blade	Good	85	R/H Mirror	Good				
5	Front Right Indicators	✓	35	Noise	✓ <td>36</td> <td>Clutch</td> <th>•</th> <td>60</td> <td>Shock Absorbers</td> <th>✓</th> <td>86</td> <td>L/H Mirror</td> <td>Good</td> <td>87</td> <td>L/F Guard</td> <td>Good</td>	36	Clutch	•	60	Shock Absorbers	✓	86	L/H Mirror	Good	87	L/F Guard	Good			
6	Front Left Indicators	✓	36	Clutch	•	37	CV Joints	✓	Wheels and Tyres		61	Left Front	6.5	mm	88	R/F Guard	Good			
7	Rear Right Indicators	✓	38	Wheel Bearing	✓	39	Wheel Balance	✓	62	Right Front	6.5	mm	63	Left Rear	6	mm	89	L/H Doors	Good	
8	Rear Left Indicators	✓	40	Gearbox (Manual)	•	41	Engine Timing	Timing Chain	64	Right Rear	6	mm	65	Spare	N/A	90	R/H Doors	Good		
9	Reversing Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	43	Replaced at (odometer reading)		66	Tools	✓	91	L/H Sill	Good	92	R/H Sill	Good			
10	Rear Reflectors	✓	Brakes		44	Front Brakes	✓ <th colspan="2">Interior</th> <td>67</td> <td>AC Operation</td> <th>✓<td>93</td><td>Boot/Tail Gate</td><td>Good</td><td>94</td><td>Front Bumper</td><td>Good</td></th>	Interior		67	AC Operation	✓ <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td> <td>94</td> <td>Front Bumper</td> <td>Good</td>	93	Boot/Tail Gate	Good	94	Front Bumper	Good		
11	Hazard Lights	✓	45	Rear Brakes	✓ <td>46</td> <td>Handbrake</td> <th>✓<td>68</td><td>Heater Fan</td><th>✓<td>95</td><td>Rear Bumper</td><td>Good</td><td>96</td><td>Roof</td><td>Good</td></th></th>	46	Handbrake	✓ <td>68</td> <td>Heater Fan</td> <th>✓<td>95</td><td>Rear Bumper</td><td>Good</td><td>96</td><td>Roof</td><td>Good</td></th>	68	Heater Fan	✓ <td>95</td> <td>Rear Bumper</td> <td>Good</td> <td>96</td> <td>Roof</td> <td>Good</td>	95	Rear Bumper	Good	96	Roof	Good			
12	Courtesy Lights	✓	Keys and Locking		47	Central Locking	✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>70</td><td>Horn</td><th>✓<td>97</td><td>Bonnet</td><td>Good</td><td>98</td><td>Fuel Cap</td><th>✓</th></th></th>	69	Seatbelts	✓ <td>70</td> <td>Horn</td> <th>✓<td>97</td><td>Bonnet</td><td>Good</td><td>98</td><td>Fuel Cap</td><th>✓</th></th>	70	Horn	✓ <td>97</td> <td>Bonnet</td> <td>Good</td> <td>98</td> <td>Fuel Cap</td> <th>✓</th>	97	Bonnet	Good	98	Fuel Cap	✓	
13	Dashboard Lights	✓	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>2</td> <td>71</td> <td>Seat Heaters</td> <th>•</th> <td>72</td> <td>Sun Visors</td> <th>✓<td>99</td><td>Mud Flaps</td><th>✓</th><td>100</td><td>WOF</td><th>✓</th></th>	49	Number of Keys	2	71	Seat Heaters	•	72	Sun Visors	✓ <td>99</td> <td>Mud Flaps</td> <th>✓</th> <td>100</td> <td>WOF</td> <th>✓</th>	99	Mud Flaps	✓	100	WOF	✓
14	Dashboard Dimmer Switch	✓	Engine		50	Oil Level	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td>74</td><td>Seats</td><td>Good</td><td>75</td><td>Carpets</td><td>Good</td><td>76</td><td>Panels</td><td>Good</td></th>	73	Sun Visors Lights/Mirrors	✓ <td>74</td> <td>Seats</td> <td>Good</td> <td>75</td> <td>Carpets</td> <td>Good</td> <td>76</td> <td>Panels</td> <td>Good</td>	74	Seats	Good	75	Carpets	Good	76	Panels	Good	
15	Number Plate Light	✓	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td>77</td><td>Dashboard</td><td>Good</td><td>78</td><td>Under Carriage</td><td>Good</td></th>	52	Performance	✓ <td>77</td> <td>Dashboard</td> <td>Good</td> <td>78</td> <td>Under Carriage</td> <td>Good</td>	77	Dashboard	Good	78	Under Carriage	Good						
16	Dashboard Warning Lights	✓	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓</th> <td colspan="10"></td>	54	Starter Motor	✓												
17	Speedo	✓																		
18	Odometer	✓																		
19	Rev Counter	•																		
20	Fuel Gauge	✓																		
21	Wipers Front/Rear	✓																		
22	Window Opener FL	✓																		
23	Window Opener FR	✓																		
24	Window Opener RL	✓																		
25	Window Opener RR	✓																		
26	Rear View Mirrors	✓																		
27	Radio (Basic Test Only)	✓																		
28	CD (Basic Test Only)	✓																		
29	Boot Open Switch	✓																		

Turners Certification Key:
✓ = Pass
× = Fail
• = Not applicable for this vehicle

Inspected by:	Dean Sinclair	Date:	16 Jan 2024
I have read and understood this condition guide:			
Name:		Signature:	