



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	25,478,413
Version:	1
Created:	23 Jan 2024

Make:	Mitsubishi	Body Style:	Wagon
Model:	Outlander	VIN:	7AT0CJ3MX24101625
Year:	2014	Odometer:	78,239 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good	
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td></th>	59	Steering Performance	✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	84	Rear Wiper Blade	Good	
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<th colspan="2">Wheels and Tyres</th><td>85</td><td>R/H Mirror</td><td>Good</td></th>	60	Shock Absorbers	✓ <th colspan="2">Wheels and Tyres</th> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	Wheels and Tyres		85	R/H Mirror	Good	
6	Front Left Indicators	✓	36	Clutch	•	61	Left Front	6	mm	86	L/H Mirror	Good		
7	Rear Right Indicators	✓	37	CV Joints	✓ <td>62</td> <td>Right Front</td> <td>6</td> <td>mm</td> <td>87</td> <td>L/F Guard</td> <td>Good</td>	62	Right Front	6	mm	87	L/F Guard	Good		
8	Rear Left Indicators	✓	38	Wheel Bearing	✓ <td>63</td> <td>Left Rear</td> <td>6</td> <td>mm</td> <td>88</td> <td>R/F Guard</td> <td>Good</td>	63	Left Rear	6	mm	88	R/F Guard	Good		
9	Reversing Lights	✓	39	Wheel Balance	✓ <td>64</td> <td>Right Rear</td> <td>6</td> <td>mm</td> <td>89</td> <td>L/H Doors</td> <td>Good</td>	64	Right Rear	6	mm	89	L/H Doors	Good		
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	65	Spare	N/A	90	R/H Doors	Good			
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	66	Tools	✓	91	L/H Sill	Good			
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	Interior		67	AC Operation	✓ <td>92</td> <td>R/H Sill</td> <td>Good</td>	92	R/H Sill	Good	
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		68	Heater Fan	✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>93</td><td>Boot/Tail Gate</td><td>Good</td></th>	69	Seatbelts	✓ <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td>	93	Boot/Tail Gate	Good
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓ <td>70</td> <td>Horn</td> <th>✓<td>94</td><td>Front Bumper</td><td>Good</td></th>	70	Horn	✓ <td>94</td> <td>Front Bumper</td> <td>Good</td>	94	Front Bumper	Good	
15	Number Plate Light	✓	45	Rear Brakes	✓ <td>71</td> <td>Seat Heaters</td> <th>✓<td>72</td><td>Sun Visors</td><th>✓<td>95</td><td>Rear Bumper</td><td>Good</td></th></th>	71	Seat Heaters	✓ <td>72</td> <td>Sun Visors</td> <th>✓<td>95</td><td>Rear Bumper</td><td>Good</td></th>	72	Sun Visors	✓ <td>95</td> <td>Rear Bumper</td> <td>Good</td>	95	Rear Bumper	Good
16	Dashboard Warning Lights	✓	46	Handbrake	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td>74</td><td>Seats</td><td>Good</td><td>96</td><td>Roof</td><td>Good</td></th>	73	Sun Visors Lights/Mirrors	✓ <td>74</td> <td>Seats</td> <td>Good</td> <td>96</td> <td>Roof</td> <td>Good</td>	74	Seats	Good	96	Roof	Good
17	Speedo	✓	Keys and Locking		47	Central Locking	✓ <td>75</td> <td>Carpets</td> <td>Good</td> <td>97</td> <td>Bonnet</td> <td>Good</td>	75	Carpets	Good	97	Bonnet	Good	
18	Odometer	✓	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>1</td> <td>76</td> <td>Panels</td> <td>Good</td> <td>98</td> <td>Fuel Cap</td> <th>✓</th>	49	Number of Keys	1	76	Panels	Good	98	Fuel Cap	✓
19	Rev Counter	•	Engine		50	Oil Level	✓ <td>77</td> <td>Dashboard</td> <td>Good</td> <td>99</td> <td>Mud Flaps</td> <th>✓</th>	77	Dashboard	Good	99	Mud Flaps	✓	
20	Fuel Gauge	✓	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td colspan="6">Turners Certification Key:</td></th>	52	Performance	✓ <td colspan="6">Turners Certification Key:</td>	Turners Certification Key:					
21	Wipers Front/Rear	✓	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓<td colspan="6">✓ = Pass</td></th>	54	Starter Motor	✓ <td colspan="6">✓ = Pass</td>	✓ = Pass					
22	Window Opener FL	✓							✗ = Fail					
23	Window Opener FR	✓							• = Not applicable for this vehicle					
24	Window Opener RL	✓												
25	Window Opener RR	✓												
26	Rear View Mirrors	✓												
27	Radio (Basic Test Only)	✓												
28	CD (Basic Test Only)	✓												
29	Boot Open Switch	✓												

Inspected by:	Dean Sinclair	Date:	23 Jan 2024
---------------	---------------	-------	-------------

**I have read and understood this condition guide:**

Name:		Signature:	
-------	--	------------	--