

Basic Vehicle Condition Guide

Report ID: 25,478,649


Version: 1

Created: 27 Feb 2024

Make: Model: Mazda Atenza **Body Style:** Sedan Year: 2017 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 23 Feb 2025 18,894 Kms 25478649 VIN: **Next Service:** 7AT0C139X24301032 28,000km Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Blair Robertson Date: 27 Feb 2024

Name:

	Pass	Fail	N/A		
Engine					
Oil level	~				
Smoke & fumes	\(\times \)				
Performance	~				
Noise	~				
Cooling System					
Coolant condition	~				
Performance	~				
Radiator / Hoses (visual)	~				
Transmission					
Operation	~				
Noise	~				
Clutch			~		
CV joints	~				
Wheel bearings	~				
Brakes					
Performance	~				
Hand Brake	~				
Tyres (lowest observed tread depth of tyres)					
Left front	-	7	mm		
Right front	-	7	mm		
Left rear		5	mm		
Right rear	5		mm		
Spare		N/A			
Suspension		1			
Suspension performance	~				
Steering performance	\(\sigma \)				
Shock absorbers	~				
Air Conditioning / Heater					
Operation	'				
Electrical / Accessories					
Head lights	<i>'</i>				
Tail lights	•				
Indicators	•				
Dashboard warning lights	\(\times \)				
Wipers (front & rear)	•				
Window winder FL	\(\times \)				
Window winder FR Window winder RL	-				
Window winder RL Window winder RR					
Rear view mirrors	V				
Radio (basic test only)	V				
CD (basic test only) Number of keys	1				
<u> </u>	1				
Central locking	•				
Remote locking					
Sat. Nav. (basic test only)	.,				
Reversing camera					

Signature: