

Basic Vehicle Condition Guide

Report ID: 25,479,661


Version: 1

Created: 08 Mar 2024

Make: Model: Toyota Estima **Body Style:** Wagon Year: 2015 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 21 Feb 2025 55,315 Kms 25479661 VIN: 7AT0H61YX24190931 **Next Service:** 65302 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

Wet

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Greg Morgan Date: 26 Feb 2024

	Pass	Fail	N/A
Engine	1		
Oil level	~		
Smoke & fumes	~		
Performance	v		
Noise	~		
Cooling System			I
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			ļ
Operation	V		
Noise	V		
Clutch			V
CV joints	~		•
Wheel bearings	~		
Brakes			
Performance	./		
Hand Brake	1		
	d denth	of tyre	26)
Tyres (lowest observed tread depth of tyres) Left front 7.0 n			
Right front	7.0		mm
Left rear	7.0 7.0		mm
Right rear	7.0		mm
Spare		N/A	
Suspension			
Suspension performance	<i>'</i>		
Steering performance	<i>'</i>		
Shock absorbers	-		
Air Conditioning / Heater			I
Operation	'		
Electrical / Accessories		I	
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	V		
Wipers (front & rear)	~		
Window winder FL	<i>v</i>		
Window winder FR	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Window winder RL	~		
Window winder RR	V		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			~
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			~

I have read and understood this condition guide.

Name:

Signature: