

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Cooling System Coolant condition V Performance SC S P SC S SC SC S SC Key: Radiator / Hoses (visual) V S = scratch Fransmission D = dent S D SC PT SC Operation V R = rustNoise V PT = paint defect C = crackClutch V P = pin dent CV joints ~ SC \* = decals S SC Wheel bearings V SC = stone chips Brakes W = significant scuffs SC S SC S SC Performance V Note: some defects & blemishes may not be displayed in the diagram Hand Brake V **Body Inspection Comments** Tyres (lowest observed tread depth of tyres) Stone chips front window screen Left front mm 5.4 **Right front** 5.1 mm Left rear 5.4 mm **Right rear** 6.2 mm Conditions During Body Inspection: Dry Spare Yes Under Carriage & Under Bonnet Inspection Comments Suspension No underbody inspection Suspension performance V Steering performance V Shock absorbers ~ Air Conditioning / Heater Operation V Interior Comments Electrical / Accessories Good Head lights Seats 1 Tail lights 1 Good Carpets Indicators ~ Good Dashboard warning lights 1 Panels Wipers (front & rear) 1 Good Dashboard Window winder FL V Window winder FR V **General Comments** Window winder RL V Window winder RR V Rear view mirrors ~ Radio (basic test only) V CD (basic test only) V Number of keys 2 V Central locking **Road Conditions During Test Drive:** Dry Remote locking V **Engine Timing Mechanism: Timing Chain** Sat. Nav. (basic test only) V Evidence of Cam Belt Replacement: Not Applicable Kms:

I have read and understood this condition guide. Name: .....

Inspected by:

Melissa Wilson

22 Feb 2024 Date:

Signature: .....

~

Reversing camera

Report ID: 25,481,831 Version: 2 Created: 22 Feb 2024

Pass

~

V

V

V

Engine

Oil level

Noise

Smoke & fumes

Performance

N/A

Fail