

Report ID: 25,487,570 Version: 1 20 Dec 2023 Created:

Make:	Mitsubishi	Model:	Mirage	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2013	Registration:	HAF779	Reg Expiry:	12 Feb 2024	Engine			
WoF Expiry:	16 Jun 2024	Odometer:	29,508 Kms	Good No:	25487570	Oil level	~		
VIN:	MMAXTA03AEH00911	Next Service:	45,000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a run mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
	SC		S P SC W SC		S P SC W	Performance	~		
Key:				5(0)-	JI JI JE W	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission	1		I
B = rust S SC W						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scurs SPW SDPW SDPW SW						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
RH wing mirror surround broken						Tyres (lowest observed tread	Tyres (lowest observed tread depth of tyres)		
						Left front 3 m			mm
						Right front	3	3	mm
						Left rear	6	5	mm
Conditions During Body Inspection: Dry						Right rear	6	5	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Front wheel drive						Suspension performance	~		
LH/R rim bent Surface rust on front subframe						Steering performance	~		
						Shock absorbers	~		
	Air Conditioning / Heater								
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	•	
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
·				•					
Inspected by: Andre Richardson Date: 20 Dec 2023									

I have read and understood this condition guide.

Name:

Signature: