

Basic Vehicle Condition Guide

Report ID: 25,489,295


Version: 2

Created: 08 Feb 2024

Make: Model: Ssangyong Korando **Body Style:** SUV Year: 2014 Registration: HSZ205 Reg Expiry: 29 Feb 2024 **Odometer:** WoF Expiry: **Good No:** 13 Oct 2024 156,567 Kms 25489295 VIN: KPTB0A18SEP171719 Next Service: 162376 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

.

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Jaykib Collins Date: 22 Dec 2023

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	\(\times \)		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	1		
Operation	~		
Noise	~		
Clutch	\(\times \)		
CV joints	~		
Wheel bearings	~		
Brakes	1		
Performance	~		Ι
Hand Brake	V		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front		.0	mm
Right front	7.0		mm
Left rear	8.0		mm
Right rear	8.0		mm
Spare	Yes		
Suspension			
Suspension performance	~		Τ
Steering performance	V		
Shock absorbers	V		
Air Conditioning / Heater			<u> </u>
Operation	V		Π
Electrical / Accessories			
Head lights	./		Τ
Tail lights	1		
Indicators	1/		
Dashboard warning lights	1		
Wipers (front & rear)	\(\times \)		
Window winder FL	~		
Window winder FR	~		
Window winder RL	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
	~		
Window winder RR	'		
Rear view mirrors	V		
Radio (basic test only)	-	-	
CD (basic test only)	~		
Number of keys	2		
Central locking	<i>'</i>		
Remote locking	'		
Sat. Nav. (basic test only)			~
Reversing camera			1

Signature: