



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	25,494,765
Version:	2
Created:	01 Feb 2024

Make:	Honda	Body Style:	Wagon
Model:	Shuttle	VIN:	7AT08G1XX24102140
Year:	2016	Odometer:	111,144 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good			
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good			
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good			
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good				
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td></th>	59	Steering Performance	✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	84	Rear Wiper Blade	Good				
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<td>61</td><td>Left Front</td><td>5.0</td><td>mm</td><td>85</td><td>R/H Mirror</td><td>Good</td></th>	60	Shock Absorbers	✓ <td>61</td> <td>Left Front</td> <td>5.0</td> <td>mm</td> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	61	Left Front	5.0	mm	85	R/H Mirror	Good		
6	Front Left Indicators	✓	36	Clutch	•	Wheels and Tyres		62	Right Front	5.0	mm	86	L/H Mirror	Good			
7	Rear Right Indicators	✓	37	CV Joints	✓ <td>63</td> <td>Left Rear</td> <td>5.0</td> <td>mm</td> <td>64</td> <td>Right Rear</td> <td>5.0</td> <td>mm</td> <td>87</td> <td>L/F Guard</td> <td>Good</td>	63	Left Rear	5.0	mm	64	Right Rear	5.0	mm	87	L/F Guard	Good	
8	Rear Left Indicators	✓	38	Wheel Bearing	✓ <td>65</td> <td>Spare</td> <td>N/A</td> <td>66</td> <td>Tools</td> <th>✓<td>88</td><td>R/F Guard</td><td>Good</td></th>	65	Spare	N/A	66	Tools	✓ <td>88</td> <td>R/F Guard</td> <td>Good</td>	88	R/F Guard	Good			
9	Reversing Lights	✓	39	Wheel Balance	✓ <td colspan="2">Interior</td> <td>67</td> <td>AC Operation</td> <th>✓<td>89</td><td>L/H Doors</td><td>Good</td></th>	Interior		67	AC Operation	✓ <td>89</td> <td>L/H Doors</td> <td>Good</td>	89	L/H Doors	Good				
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	68	Heater Fan	✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>90</td><td>R/H Doors</td><td>Good</td></th>	69	Seatbelts	✓ <td>90</td> <td>R/H Doors</td> <td>Good</td>	90	R/H Doors	Good			
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	70	Horn	✓ <td>71</td> <td>Seat Heaters</td> <td>•</td> <td>91</td> <td>L/H Sill</td> <td>Good</td>	71	Seat Heaters	•	91	L/H Sill	Good			
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	72	Sun Visors	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td>92</td><td>R/H Sill</td><td>Good</td></th>	73	Sun Visors Lights/Mirrors	✓ <td>92</td> <td>R/H Sill</td> <td>Good</td>	92	R/H Sill	Good			
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		74	Seats	Average	75	Carpets	Average	93	Boot/Tail Gate	Good			
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓ <td>76</td> <td>Panels</td> <td>Average</td> <td>77</td> <td>Dashboard</td> <td>Average</td> <td>94</td> <td>Front Bumper</td> <td>Good</td>	76	Panels	Average	77	Dashboard	Average	94	Front Bumper	Good	
15	Number Plate Light	✓	45	Rear Brakes	✓ <td>46</td> <td>Handbrake</td> <th>✓<td colspan="2">Turners Certification Key:</td><td>✓</td><td>= Pass</td><td>×</td><td>= Fail</td><td>•</td><td>= Not applicable for this vehicle</td></th>	46	Handbrake	✓ <td colspan="2">Turners Certification Key:</td> <td>✓</td> <td>= Pass</td> <td>×</td> <td>= Fail</td> <td>•</td> <td>= Not applicable for this vehicle</td>	Turners Certification Key:		✓	= Pass	×	= Fail	•	= Not applicable for this vehicle	
16	Dashboard Warning Lights	✓	Keys and Locking		47	Central Locking	✓ <td colspan="2"></td> <td>48</td> <td>Remote Locking</td> <th>✓<td colspan="2"></td><td>95</td><td>Rear Bumper</td><td>Good</td></th>			48	Remote Locking	✓ <td colspan="2"></td> <td>95</td> <td>Rear Bumper</td> <td>Good</td>			95	Rear Bumper	Good
17	Speedo	✓	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>2</td> <td colspan="2"></td> <td>96</td> <td>Roof</td> <td>Good</td> <td>97</td> <td>Bonnet</td> <td>Good</td>	49	Number of Keys	2			96	Roof	Good	97	Bonnet	Good	
18	Odometer	✓	Engine		50	Oil Level	✓ <td colspan="2"></td> <td>98</td> <td>Fuel Cap</td> <th>✓<td colspan="2"></td><td>99</td><td>Mud Flaps</td><th>✓</th></th>			98	Fuel Cap	✓ <td colspan="2"></td> <td>99</td> <td>Mud Flaps</td> <th>✓</th>			99	Mud Flaps	✓
19	Rev Counter	✓	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td colspan="2"></td><td>100</td><td>WOF</td><th>✓<td colspan="2"></td><td></td></th></th>	52	Performance	✓ <td colspan="2"></td> <td>100</td> <td>WOF</td> <th>✓<td colspan="2"></td><td></td></th>			100	WOF	✓ <td colspan="2"></td> <td></td>				
20	Fuel Gauge	✓	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓<td colspan="2"></td><td></td><td></td><td></td><td></td><td></td><td></td></th>	54	Starter Motor	✓ <td colspan="2"></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>									
21	Wipers Front/Rear	✓															
22	Window Opener FL	✓															
23	Window Opener FR	✓															
24	Window Opener RL	✓															
25	Window Opener RR	✓															
26	Rear View Mirrors	✓															
27	Radio (Basic Test Only)	✓															
28	CD (Basic Test Only)	•															
29	Boot Open Switch	✓															

Inspected by:	Greg Morgan	Date:	26 Jan 2024
I have read and understood this condition guide:			
Name:		Signature:	