



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	25,499,453
Version:	1
Created:	10 Feb 2024

Make:	Nissan	Body Style:	Hatchback
Model:	Note	VIN:	7AT0DH79X24023786
Year:	2016	Odometer:	65,472 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good		
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good		
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good		
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good			
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td></th>	59	Steering Performance	✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	84	Rear Wiper Blade	Good			
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<td>61</td><td>Left Front</td><td>6.3</td><td>mm</td><td>85</td><td>R/H Mirror</td><td>Good</td></th>	60	Shock Absorbers	✓ <td>61</td> <td>Left Front</td> <td>6.3</td> <td>mm</td> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	61	Left Front	6.3	mm	85	R/H Mirror	Good	
6	Front Left Indicators	✓	36	Clutch	•	Wheels and Tyres		62	Right Front	6.4	mm	86	L/H Mirror	Good		
7	Rear Right Indicators	✓	37	CV Joints	✓ <td>63</td> <td>Left Rear</td> <td>6.7</td> <td>mm</td> <td>64</td> <td>Right Rear</td> <td>6.6</td> <td>mm</td> <td>87</td> <td>L/F Guard</td> <td>Good</td>	63	Left Rear	6.7	mm	64	Right Rear	6.6	mm	87	L/F Guard	Good
8	Rear Left Indicators	✓	38	Wheel Bearing	✓ <td>65</td> <td>Spare</td> <td>N/A</td> <td>66</td> <td>Tools</td> <th>✓<td>88</td><td>R/F Guard</td><td>Good</td></th>	65	Spare	N/A	66	Tools	✓ <td>88</td> <td>R/F Guard</td> <td>Good</td>	88	R/F Guard	Good		
9	Reversing Lights	✓	39	Wheel Balance	✓ <th colspan="2">Interior</th> <td>67</td> <td>AC Operation</td> <th>✓<td>89</td><td>L/H Doors</td><td>Good</td></th>	Interior		67	AC Operation	✓ <td>89</td> <td>L/H Doors</td> <td>Good</td>	89	L/H Doors	Good			
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	68	Heater Fan	✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>90</td><td>R/H Doors</td><td>Good</td></th>	69	Seatbelts	✓ <td>90</td> <td>R/H Doors</td> <td>Good</td>	90	R/H Doors	Good		
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	70	Horn	✓ <td>71</td> <td>Seat Heaters</td> <td>•</td> <td>91</td> <td>L/H Sill</td> <td>Good</td>	71	Seat Heaters	•	91	L/H Sill	Good		
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	72	Sun Visors	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td>92</td><td>R/H Sill</td><td>Good</td></th>	73	Sun Visors Lights/Mirrors	✓ <td>92</td> <td>R/H Sill</td> <td>Good</td>	92	R/H Sill	Good		
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		74	Seats	Good	75	Carpets	Good	93	Boot/Tail Gate	Good		
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓ <td>76</td> <td>Panels</td> <td>Good</td> <td>77</td> <td>Dashboard</td> <td>Good</td> <td>94</td> <td>Front Bumper</td> <td>Good</td>	76	Panels	Good	77	Dashboard	Good	94	Front Bumper	Good
15	Number Plate Light	✓	45	Rear Brakes	✓ <td>46</td> <td>Handbrake</td> <th>✓<th colspan="2">Turners Certification Key:</th><td>95</td><td>Rear Bumper</td><td>Good</td></th>	46	Handbrake	✓ <th colspan="2">Turners Certification Key:</th> <td>95</td> <td>Rear Bumper</td> <td>Good</td>	Turners Certification Key:		95	Rear Bumper	Good			
16	Dashboard Warning Lights	✓	Keys and Locking		47	Central Locking	✓ <td>96</td> <td>Roof</td> <td>Good</td> <td>97</td> <td>Bonnet</td> <td>Good</td>	96	Roof	Good	97	Bonnet	Good			
17	Speedo	✓	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>2</td> <td>98</td> <td>Fuel Cap</td> <th>✓</th> <td>99</td> <td>Mud Flaps</td> <th>✓</th>	49	Number of Keys	2	98	Fuel Cap	✓	99	Mud Flaps	✓		
18	Odometer	✓	Engine		50	Oil Level	✓ <td>100</td> <td>WOF</td> <th>✓</th>	100	WOF	✓						
19	Rev Counter	✓	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td colspan="5"></td></th>	52	Performance	✓ <td colspan="5"></td>								
20	Fuel Gauge	✓	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓<td colspan="5"></td></th>	54	Starter Motor	✓ <td colspan="5"></td>								
21	Wipers Front/Rear	✓														
22	Window Opener FL	✓														
23	Window Opener FR	✓														
24	Window Opener RL	✓														
25	Window Opener RR	✓														
26	Rear View Mirrors	✓														
27	Radio (Basic Test Only)	✓														
28	CD (Basic Test Only)	✓														
29	Boot Open Switch	✓														

Inspected by:	Hugh Stuart	Date:	10 Feb 2024
I have read and understood this condition guide:			
Name:		Signature:	