



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	25,499,476
Version:	1
Created:	08 Feb 2024

Make:	Toyota	Body Style:	Hatchback
Model:	Auris	VIN:	7AT0H659X24006723
Year:	2016	Odometer:	92,358 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓	83	Front Wiper Blades	Good	
4	High Stop Light	✓	Transmission and Drive		Wheels and Tyres		59	Steering Performance	✓	84	Rear Wiper Blade	Good		
5	Front Right Indicators	✓	34	Operation	✓	60	Shock Absorbers	✓	85	R/H Mirror	Good			
6	Front Left Indicators	✓	35	Noise	✓	61	Left Front	6.6 mm	86	L/H Mirror	Good			
7	Rear Right Indicators	✓	36	Clutch	•	62	Right Front	6.8 mm	87	L/F Guard	Good			
8	Rear Left Indicators	✓	37	CV Joints	✓	63	Left Rear	6.2 mm	88	R/F Guard	Good			
9	Reversing Lights	✓	38	Wheel Bearing	✓	64	Right Rear	6.7 mm	89	L/H Doors	Good			
10	Rear Reflectors	✓	39	Wheel Balance	✓	65	Spare	Yes	90	R/H Doors	Good			
11	Hazard Lights	✓	40	Gearbox (Manual)	•	66	Tools	✓	91	L/H Sill	Good			
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	Interior		67	AC Operation	✓	92	R/H Sill	Good	
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	68	Heater Fan	✓	93	Boot/Tail Gate	Good			
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		69	Seatbelts	✓	94	Front Bumper	Good			
15	Number Plate Light	✓	Brakes		Seats <td>70</td> <td>Horn</td> <td>✓</td> <td>95</td> <td>Rear Bumper</td> <td>Good</td>		70	Horn	✓	95	Rear Bumper	Good		
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	71	Seat Heaters	•	96	Roof	Good			
17	Speedo	✓	45	Rear Brakes	✓	72	Sun Visors	✓	97	Bonnet	Good			
18	Odometer	✓	46	Handbrake	✓	73	Sun Visors Lights/Mirrors	✓	98	Fuel Cap	✓			
19	Rev Counter	✓	Keys and Locking		Carpets <td>74</td> <td>Seats</td> <td>Good</td> <td>99</td> <td>Mud Flaps</td> <td>✓</td>		74	Seats	Good	99	Mud Flaps	✓		
20	Fuel Gauge	✓	47	Central Locking	✓	75	Carpets	Good	100	WOF	✓			
21	Wipers Front/Rear	✓	48	Remote Locking	✓	76	Panels	Good						
22	Window Opener FL	✓	49	Number of Keys	2	77	Dashboard	Good						
23	Window Opener FR	✓	Engine		Mirrors <td></td> <td></td> <td></td> <td></td> <td></td>									
24	Window Opener RL	✓	50	Oil Level	✓									
25	Window Opener RR	✓	51	Smokes and Fumes	✓									
26	Rear View Mirrors	✓	52	Performance	✓									
27	Radio (Basic Test Only)	✓	53	Noise	✓									
28	CD (Basic Test Only)	•	54	Starter Motor	✓									
29	Boot Open Switch	✓												

**Turners Certification Key:**  
✓ = Pass  
× = Fail  
• = Not applicable for this vehicle

Inspected by:	Hugh Stuart	Date:	08 Feb 2024
I have read and understood this condition guide:			
Name:		Signature:	