

Report ID: 25,499,917 Version: 1 13 Mar 2024 Created:

Make:	Mazda	Model:	Axela	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2018	Registration:		Reg Expiry:		Engine			
WoF Expiry:	08 Mar 2025	Odometer:	30,804 Kms	Good No:	25499917	Oil level	~		
VIN:		Next Service:	40,000 km	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
			SC W			Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	sc			715	HIV	Operation	~		
PT = paint defe		F I		$\left[\left(\right) \right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	HE				7414	CV joints	~		
* = decals	s 616			The second		Wheel bearings	V		
SC = stone chips W = significant scuffs						Brakes			
vv = significant	SC					Performance	~		
Body Incr	oction Commonts	Note: som	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	V		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			es)
									mm
						Right front	6	5	mm
						Left rear	6	5	mm
Conditions During Body Inspection: Dry					Right rear	6 mm		mm	
						Spare	No		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
FWD.						Suspension performance	~		
						Steering performance	~		
Shoc						Shock absorbers	~		
						Air Conditioning / Heater	ning / Heater		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	V		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
· · · · · · · · · · · · · · · · · · ·						Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Imraan Bryant Date: 13 Mar 2024									

I have read and understood this condition guide.

Name:

Signature: