

Basic Vehicle Condition Guide

Service History:

Report ID: 25,500,001

Version: 2

Created: 13 Mar 2024


Make:HondaModel:FreedBody Style:Year:2012Registration:Reg Expiry:WoF Expiry:11 Mar 2025Odometer:129,150 KmsGood No:25500001

Note: This report is not a warranty

VIN:

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Next Service: 139,100kms



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Front wheel drive.

| Interior Commen | <u>ts</u> |
|-----------------|-----------|
| Seats | Good |
| Carpets | Good |
| Panels | Good |
| Dashboard | Good |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Takaya Murayama

| Cleate | u | | | | |
|-------------------------------------|---------------------------------------|---------|----------|--|--|
| | Pass | Fail | N/A | | |
| Engine | | | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | V | | | | |
| Performance | ~ | | | | |
| Noise | ~ | | | | |
| Cooling System | | | • | | |
| Coolant condition | ~ | | | | |
| Performance | ~ | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | ! | | |
| Operation | ' | | | | |
| Noise | ~ | | | | |
| Clutch | | | ~ | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | <u> </u> | | |
| Performance | ~ | | | | |
| Hand Brake | <i>'</i> | | | | |
| Tyres (lowest observed tread | depth | of tyre |) | | |
| Left front 4 mm | | | | | |
| Right front | 4 | | mm | | |
| Left rear | 4 | | mm | | |
| Right rear | | | mm | | |
| | 4 N/A | | | | |
| Spare N/A Suspension | | | | | |
| Suspension performance | ·/ | | | | |
| Steering performance | ./ | | | | |
| Shock absorbers | • | | | | |
| Air Conditioning / Heater | • | | | | |
| | ., | | 1 | | |
| Operation Electrical / Accessories | • | | | | |
| Head lights | | | | | |
| | | | | | |
| Tail lights | - | | | | |
| Indicators | • | | | | |
| Dashboard warning lights | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | | | |
| Wipers (front & rear) | • | | | | |
| Window winder FL | • | | | | |
| Window winder FR | ~ | | | | |
| Window winder RL | <i>V</i> | | | | |
| Window winder RR | V V | | | | |
| Rear view mirrors | | | | | |
| Radio (basic test only) | ' | | | | |
| CD (basic test only) | ~ | | | | |
| Number of keys | 1 | | 1 | | |
| Central locking | ~ | | | | |
| Remote locking | ~ | | | | |
| Sat. Nav. (basic test only) | | | ~ | | |
| Reversing camera | ~ | | | | |

13 Mar 2024

Date:

| have read and understood this condition guide. | Name: | Signature: |
|--|-------|------------|