

Basic Vehicle Condition Guide

Report ID: 25,500,119

Version: 1

Created: 01 Mar 2024


Make:ToyotaModel:CorollaBody Style:HatchbackYear:2019Registration:Reg Expiry:

 WoF Expiry:
 28 Feb 2025
 Odometer:
 73,210 Kms
 Good No:
 25500119

 VIN:
 Next Service:
 83,200 km
 Service History:
 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

FWD.

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

Genera	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Imraan Bryant Date: 01 Mar 2024

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	V V		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	\(\triangle \)		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front		4	mm
Right front		4	mm
Left rear		4	mm
Right rear		4	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	\(\times \) \(\t		
Window winder FL	~		
Window winder FR			
Window winder RL	V		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			~
Number of keys	1		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		

Signature: