

Report ID: 25,500,174 Version: 2 13 Mar 2024 Created:

Make:	Honda	Model:	FIT	Body Style:			Pass	Fail	N/A	
Year:	2013	Registration:		Reg Expiry:		Engine				
WoF Expiry:	28 Feb 2025	Odometer:	76,676 Kms	Good No: 25500174		Oil level	~			
VIN:		Next Service:	86,673 km	Service History: No		Smoke & fumes	~			
						Performance	~			
	port is not a warranty		for age and mileage	Parts have not been dismantled o	r	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition	~			
					٦	Performance	~			
Key:		-0	S S	SP SP		Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent	s sc					Operation	~			
R = rust PT = paint defe	act TIP					Noise	~			
C = crack						Clutch	•		~	
P = pin dent	H					CV joints	~			
* = decals	PT QIE				٦	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs SC SC SC SC						Performance	~			
		Note: son	he defects & blemishes	may not be displayed in the diagram		Hand Brake	~			
Body Insp	pection Comments	5		may not be alsplayed in the alagram			-	oftyre))	
						Tyres (lowest observed tread depth of tyres) Left front 6 mm				
									mm	
						Right front		7	mm	
						Left rear		5	mm	
Conditions During Body Inspection: Dry									mm	
Under Carriage & Under Bonnet Inspection Comments						Spare No				
FWD.	inage & onder bo	metinspectic	<u>on comments</u>			Suspension				
FWD.						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments Good						Electrical / Accessories				
Seats	Good					Head lights	~			
Carpets	Good					Tail lights	~			
						Indicators	~			
Panels	Good					Dashboard warning lights	~			
Derth	Good					Wipers (front & rear)	~			
Dashboa	ra					Window winder FL	~			
	_					Window winder FR	~			
General Comments						Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		-	
Inspected by: Marlon Espena Date: 13 Mar 2024										

I have read and understood this condition guide.

Name:

Signature: