

Report ID: 25,500,277 Version: 2 28 Feb 2024 Created:

Make:	Subaru	Model:	Impreza	Body Style:	Wagon		Pass	Fail	N/A
Year:	2015	Registration:		Reg Expiry:	-	Engine			
WoF Expiry:	27 Feb 2025	Odometer:	59,294 Kms	Good No:	25500277	Oil level	~		
VIN:		Next Service:	69,000 km	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust				715	HIV	Operation	~		
PT = paint defe				$\left[\left(\right) \right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	HIE				74114	CV joints	~		
* = decals	MA			Tool .		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w = significan						Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	olayed in the diagram	Hand Brake	~		
body inspection comments					Tyres (lowest observed tread depth of tyres)			s)	
					Left front	7 mm		mm	
						Right front	8	3	mm
						Left rear	4	ł	mm
Conditions During Body Inspection: Dry Right rear						Right rear	5	5	mm
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
AWD						Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
Air Conditioning / Hea									
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Comoto	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Good					Wipers (front & rear)	<		
Dashboa	ra					Window winder FL	<		
	-					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry Central locking									
	-		·			Remote locking	~		
-	ming Mechanism:	Timing (Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Allan Young Date: 28 Feb 2024									
Inspected by. And Found Date: 20 Feb 2024									

I have read and understood this condition guide.

Name:

Signature: