

Report ID: 25,505,236 Version: б 02 May 2024 Created:

Make:	BMW	Model:	1161	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2011	<b>Registration:</b>	NNL960	<b>Reg Expiry:</b>	09 Jul 2024	Engine			L
WoF Expiry:	06 Apr 2024	Odometer:	86,681 Kms	Good No:	25505236	Oil level	~		
VIN:	WBA1A120X0E640642	Next Service:	87,000 km	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
	S W		SC			Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust S PT SC W						Operation 🖌			
PT = paint defe				$\left( \left  \left( \right) \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				7414	CV joints			~
* = decals	s sc 916			-NG		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W D						Performance	~		
Dealerteen		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	V		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
								mm	
						Right front	5		mm
						Left rear	5		mm
Conditions During Pody Inspection: Dry						Right rear			 mm
Conditions During Body Inspection: Dry						Spare N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-					Suspension performance	~		
						Steering performance	• •		
						Shock absorbers	~		
						Air Conditioning / Heater	•		I
						Operation	V		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Jeals						Tail lights	v v		
Carpets	Good					Indicators	v v		
Devision	Good					Dashboard warning lights	v v		
Panels						Wipers (front & rear)	v v		
Dashboa	rd Good					Window winder FL			
						Window winder FL	<b>v</b>		
General (	Comments					Window winder FR	<b>v</b>		
							<b>v</b>		
						Window winder RR	V		
						Rear view mirrors	~		
						Radio (basic test only)	V		
						CD (basic test only)	<b>v</b>		Ĺ
						Number of keys	1		
Road Con	ditions During Test	: Drive:	Dry			Central locking	~		
Engine Tir	ming Mechanism:	Timing (	Chain			Remote locking	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
		ciriciti. N		11113.		Reversing camera			~
Inspected by: Allan Young Date: 02 May 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....