

Report ID: 25,514,375 Version: 1 12 Jan 2024 Created:

Make:	Holden	Model:	Barina	Body Style:	Sedan		Pass	Fail	N/A
Year:	2016	<b>Registration:</b>	JQA400	Reg Expiry:	30 Mar 2024	Engine		l	1
WoF Expiry:	19 Apr 2024	Odometer:	83,906 Kms	Good No:	25514375	Oil level	~		
VIN:	KL3TA69E9GB626983	Next Service:	96000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~	L	
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
	[ w		P SC W P		S SC	Performance	~		
Key:		-0	PSCW	-01-	330	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	sc w			715	S SC	Operation	~		
PT = paint def		F I		$\left( \left  \left( \right) \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HE				7414	CV joints	~		
* = decals	PSC 916					Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC W P SC W P SC S W P SC						Performance	~		
Bodylas		Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						<b>Tyres</b> (lowest observed tread depth of tyres)			es)
Small chips front screen Decal peeling LR door						Left front 3.8			mm
Scuffing front bumper lip						Right front	4		mm
						Left rear	4		mm
Conditions During Body Inspection: Dry						Right rear	4.7 m		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments					Suspension				
Oil leak und	ler engine					Suspension performance	~		
All else ok						Steering performance	~		
All else ok						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets	Guou					Indicators	~		
Panels	Good					Dashboard warning lights	~		
	. Good					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	1					Window winder FR	~		
General Comments					Window winder RL	~			
Vehicle drove very well						Window winder RR	~	-	
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	L	1
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
						L	1		1
Inspecte	d by: Mike Greenfield					Date: 12 Jan 202	24		

I have read and understood this condition guide.

Name: .....

Signature: .....