

Report ID: 25,527,324 Version: 1 30 Jan 2024 Created:

| Make: | Audi | Model: | A4 | Body Style: | Sedan | | Pass | Fail | N/A |
|--|------------------------|-----------------|------------------------|---------------------------------------|----------------------|--|------|--------|-----|
| Year: | 2005 | Registration: | CQC160 | Reg Expiry: | 19 Oct 2024 | Engine | | | |
| WoF Expiry: | 22 Sep 2024 | Odometer: | 175,000 Kms | Good No: | 25527324 | Oil level | ~ | | |
| VIN: | WAUZZZ8E35A48800! | Next Service: | Due | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | avation is made | for one and miles as | Danta hava nat | heen discontined or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| | | | | | | Coolant condition | | | |
| | | | | | | Performance | ~ | | |
| Key: | SC | -0 | SP SP | -01- | SP | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent | SC DE | | | ZIS | HIL S | Operation | ~ | | |
| R = rust PT = paint defe | | | | $\left(\left \right\rangle \right)$ | | Noise | ~ | | |
| C = crack | | | | + | | Clutch | | | ~ |
| P = pin dent | HID | | | | 74 <u>11</u> | CV joints | ~ | | |
| * = decals | sc 916 | | | -No- | | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significan | t scuffs SC | | SP S | | S | Performance | ~ | | |
| Podylocr | action Commonts | Note: son | ne defects & blemishes | s may not be disp | layed in the diagram | Hand Brake | ~ | | |
| Body Inspection Comments | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front | 3.0 |) | mm |
| | | | | | | Right front | 5.0 |) | mm |
| | | | | | | Left rear | 2.5 | 5 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 3.0 | 3.0 mm | |
| | | | | | | Spare | Yes | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | nts leaking grease. | | | | | Suspension performance | ~ | | |
| Engine oil le | eak. | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | I | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Average | | | | | Head lights | ~ | | |
| | Average | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | |
| | Average | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General Comments | | | | | Window winder RL | ~ | | | |
| Hood lining sagging. Lh inner tail light n/w. | | | | | Window winder RR | ~ | | | |
| | sole lid broken. | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| L | | | | | | Number of keys | 1 | | |
| Road Con | ditions During Test | t Drive: | Dry | | | Central locking | ~ | | |
| | | | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| Inspected by: Reuben Harvey Date: 25 Jan 2024 | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: