

Report ID: 25,530,066 Version: 1 04 Mar 2024 Created:

Make:	Toyota	Model:	Hiace	Body Style: Van		Pass	Fail	N/A
Year:	2018	Registration:		Reg Expiry:	Engine			
	27 Feb 2025	Odometer:	93,736 Kms	Good No: 25530066	Oil level	~		
VIN:	7AT0H60FX24010166	Next Service:		Service History: No	Smoke & fumes	~		
					Performance	~		
	port is not a warranty				Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends					Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					Coolant condition	~		
		_			Performance	~		
Key:		-0	P SC		Radiator / Hoses (visual)	~		
S = scratch					Transmission			
					Operation 🖌			
R = rust		Noise	~					
PT = paint defe	ect M	Clutch	V					
C = crack P = pin dent								~
*= decals SC PIP					CV joints	~		
SC = stone chips					Wheel bearings	5		
W = significant scuffs					Brakes			
					Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram					Hand Brake	~		
					Tyres (lowest observed tread depth of tyres)			
					Left front	7.0		mm
					Right front	7.	0	mm
					Left rear	6.	0	mm
Conditions During Body Inspection: Dry					Right rear	4.0 mr		mm
					Spare Yes			
Under Carriage & Under Bonnet Inspection Comments					Suspension			
					Suspension performance	~		
					Steering performance	~		
		Shock absorbers	~					
					Air Conditioning / Heater			
					Operation 🖌			
Interior Comments					Electrical / Accessories			
Seats	Average				Head lights	~		
Carpote	Average				Tail lights	~		
Carpets					Indicators	~		
Panels	Average				Dashboard warning lights	~		
	Average				Wipers (front & rear)	~		
Dashboa	ra				Window winder FL	~		
	_				Window winder FR	~		
<u>General Comments</u>					Window winder RL			~
					Window winder RR			<
					Rear view mirrors	~		
					Radio (basic test only)	~		
		CD (basic test only)	~					
					Number of keys	1		
Road Conditions During Test Drive: Dry Central locking								
	-				Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)								~
Evidence of Cam Belt Replacement: Not Applicable Kms:					Reversing camera	~		
Inspected by: Chris Buckley Date: 04 Mar 2024								

I have read and understood this condition guide.

Name:

Signature: