

Basic Vehicle Condition Guide

Report ID: 25,530,084


Version: 2

Created: 07 Mar 2024

Make: Model: Mitsubishi Outlander **Body Style:** Wagon Year: 2013 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 28 Feb 2025 59,502 Kms 25530084 VIN: 7AT0CJ3MX24005175 **Next Service:** 69,498 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Kyle Kelly Date: 03 Mar 2024

Name:

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
~		
~		
		~
~		
~		
1		
~		
d depth	of tyre	es)
5	.0	mm
5	.0	mm
5.0		mm
5.0		mm
No		
~		
~		
~		
ı		1
~		
		1
~		
~		
~		
~		
~		
~		
<i>v</i>		
~		
\(\triangle \)		
~		
\(\times \)		
\(\times \)		
\(\times \)		v
V V V V V V		· ·
V V V V V V		<i>'</i>
V V V V V V		v
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ

Signature: