

Basic Vehicle Condition Guide

Report ID: 25,530,218

Version: 2

Created: 01 Mar 2024

Make: Model: Subaru ΧV **Body Style:** Hatchback

Year: 2018

WoF Expiry:

VIN:

Registration: **Odometer:** 72,860 Kms

Reg Expiry: **Good No:**


25530218

7AT0GF1XX24078020 **Next Service:** 82852 Service History:

Note: This report is not a warranty

28 Feb 2025

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Fitted with snow tires all around

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

	_
General	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Sione Mae

	_					
	Pass	Fail	N/A			
Engine						
Oil level	~					
Smoke & fumes	\(\tau \)					
Performance	~					
Noise	~					
Cooling System						
Coolant condition	~					
Performance	~					
Radiator / Hoses (visual)	~					
Transmission						
Operation	~					
Noise	~					
Clutch			~			
CV joints	~					
Wheel bearings	~					
Brakes						
Performance	~					
Hand Brake	~					
Tyres (lowest observed tread depth of tyres)						
Left front	7	.0	mm			
Right front	7.0		mm			
Left rear	7.0		mm			
Right rear	7.0		mm			
Spare N/A						
Suspension						
Suspension performance	~					
Steering performance	<i>V</i>					
Shock absorbers	~					
Air Conditioning / Heater						
Operation	~					
Electrical / Accessories						
Head lights	~					
Tail lights	~					
Indicators	~					
Dashboard warning lights	V V V V V					
Wipers (front & rear)	~					
Window winder FL	~					
Window winder FR	~					
Window winder RL	~					
Window winder RR	~					
Rear view mirrors	\(\times \)					
Radio (basic test only)	~					
CD (basic test only)	~					
Number of keys	2	<u> </u>	L			
Central locking	·					
Remote locking	~					
Sat. Nav. (basic test only)	<u> </u>		~			
Land (Subsected Colly)			<u> </u>			

01 Mar 2024

1

Reversing camera