

Report ID: 25,530,256 Version: 1 12 Mar 2024 Created:

Make:	Subaru	Model:	XV	Body Style: Hatchback		Pass	Fail	N/A
Year:	2013	Registration:		Reg Expiry:	Engine	_		
WoF Expiry:		Odometer:	118,202 Kms	Good No: 25530256	Oil level	~		
VIN:	7AT0GF1XX24034760	Next Service:		Service History: No	Smoke & fumes	~		
				• •••	Performance	~		
	port is not a warranty				Noise	~		
This report is diagnostic te	s a guide only. Conside sting undertaken. The	eration is made vehicle has beer	for age and mileag driven up to 50km	e. Parts have not been dismantled or /h from cold. The Vendor recommends	Cooling System	•		
a full mechan	ical inspection prior to	purchase and th	nis can be arranged	for an additional charge.	Coolant condition	~		
		_			Performance	~		
Key:		-0			Radiator / Hoses (visual)	~		
S = scratch	STE	A CO	$\overline{\neg}$		Transmission	•		
D = dent	w GlE				Operation	~		
R = rust				T OHH	Noise	~		
PT = paint def C = crack					Clutch			~
P = pin dent					CV joints	~		
* = decals	sc pp				Wheel bearings	~		
SC = stone chips					Brakes	V		
W = significan	t scuffs	$- \emptyset$	S		Performance	~		
		Note: som		es may not be displayed in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						•		
					Tyres (lowest observed tread depth of tyres) Left front 4.0			
						4.0		mm
					Right front Left rear	4.0		mm
								mm
Conditions During Body Inspection: Dry					Right rear	4.0	4.0 mn	
Under Carriage & Under Bonnet Inspection Comments					Spare N/A			
	indge a onder bor	<u>ince inspectie</u>	<u>eonnents</u>		Suspension			
					Suspension performance	~		
					Steering performance Shock absorbers	~		
						~		ı
					Air Conditioning / Heater			
Interior Comments					Operation			
					Electrical / Accessories			
Seats	5				Head lights	~		
Carpets	Average				Tail lights	~		
	Average				Indicators	~		
Panels	//verage				Dashboard warning lights	~		
Dashboa	Average				Wipers (front & rear)	~		
					Window winder FL	~		
<u>General Comments</u>					Window winder FR	~		
					Window winder RL	~		
					Window winder RR	~		
					Rear view mirrors	~		
					Radio (basic test only)	~		
					CD (basic test only)			~
[Number of keys	1		
Road Conditions During Test Drive: Dry Central locking						~		
Engine	ming Machanism	Timein - (- -		Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms: Beversing camera								~
Evidence	oi Cam Beit Replac	ement: N	lot Applicable	Kms:	Reversing camera	~		L
Inspecte	d by: Greg Morgan				Date: 08 Mar 20	24		

I have read and understood this condition guide.

Name:

Signature: